

**EARTH REMOVAL STORMWATER ADVISORY COMMITTEE  
SEPTEMBER 22, 2015  
MINUTES**

Chairman Perkins called the meeting to order at 7:00 PM

Members present: Perkins, Capes, Delaney, Hanninen, and Swezey

**COMPLIANCE ISSUES**

The Committee discussed a number of compliance issues including:

**NESSP Temple, Boston Road** – The site of the NESSP Temple needs stabilization before the end of the construction season. Dust has been an on-going issue. The Committee will send the NESSP Temple and general contractor a letter stating that site must be properly stabilized and all erosion control in place prior to October 30, 2015.

**Chamberlains Mill** – There are several minor erosion problems at the site. The motion was made by Hanninen, seconded by Delaney, to send a letter to developer Robert Kiley stating that he must follow the recommendations in the Nitsch Engineer report dated September 23, 2015 and that that site must be properly stabilized before the end of the construction season. The motion passed unanimously.

**253 Hill Road** – The Committee reviewed the as-built plans for the single family lot at 253 Hill Road and had concerns about the berm along the side of the driveway and in the right-of-way of Hill Road. Member Delaney said the berm in Hill Road will be a problem when the DPW plows the road. The Committee will notify the owner and request that he remove the berm immediately.

**157 & 197 Maple Avenue** - The two single-family lots are stable and the on-going flooding issues on Maple Avenue appear to be corrected. The Committee will continue to monitor the situation.

Meeting adjourned at 7:30 PM

Respectfully submitted,

Michelle Collette  
Earth Removal/Stormwater Inspector