MEL BLACKMAN
MASTER LEAD PAINT INSPECTOR
P.O. BOX 358 – STONEHAM, MA. 02180
OFFICE: PHONE 781- 665 – 3806 – CELL: 781 - 820 – 8611
E-MAIL: melblackman@gmail.com

Lead Inspection / Risk Assessment

St.# 145 Street Name MAIN Street Type ST. Unit DAYCARE
City GROTON Zip Code 01450

Owner Name: OMNI PROPERTIES C/O JOHN AMARAL
Owner Address: 6 LYBERTYWAY, SUITE 203, WESTFORD, MA 01886
Contact Information: 978-835-0629
Client Name (if different from owner):
Client Address: e-mai;jamaral@omniproperties.com

Number of Rooms in Unit: 13
Property Type:
- [ ] Single Family
- [ ] Multi Family # of Units:
- [ ] Condominium # of Units:
- [x] Day Care [ ] Other:

Laundry in Basement? [ ] Yes [x] No
Finished Space in Basement? [ ] Yes [x] No
Possible Pb Water Service Line [ ] Yes [ ] No [x] Not Tested
Testing Method Used
Na_2S Expiration Date: / /
X-Ray Fluorescence
Model: LPA-1 Serial # 1409

- [ ] Demarcation Lines
- [ ] Submitted for Compliance Evaluation

Key	Lead Column
COV	Covered
DC	Drop Ceiling
MET	Metal
MR	Metal Rep. Window
NA	Not Accessible
NC	No Coating
	Tile (testing suggested)
	Vinyl Baseboard
VR	Vinyl Rep. Window

Key	Delead/IC Method Column	Key	Delead/IC Method Column
COV	Covered	REM	Removed
DIP	Dipped	REP	Replaced
ENC	Encapsulated	SCR	Scraped
INT	Intact	SFR	Storm Frame Removed
MI	Made Intact	SLD	Sealed
PRE	Prepared for Enc.	STP	Stripped
	Component Does Not Exist	VR/MR	Vinyl/Metal Rep Window

Comments / Notes:

Floor# 1st (level within building of unit being inspected) Floor# Basement





Property Diagram / Unit Labels



Pb (lead) equal to or greater than 1.0 mg/cm² with x-ray fluorescence or positive with Na_2S is Dangerous.

XRF Calibration Recorded in Log Book [x] ✓ - Check off when complete
Address Verified through USPS [x] ✓ - Check off when complete
Research on Lead Related History for Address [x] ✓ - Check off when complete
www.state.ma.us/dph/clppp or 800-532-9571

MEL BLACKMAN
Inspector's Name (print)
LI/RA - revised 06/17

M-1377
License #

Signature

08 / 27 / 18
Date

CAT INSPECTION SERVICES
151 ASHBURNHAM HILL ROAD
FITCHBURG, MA 01420
(978) 345-7273

Lead Inspection / Risk Assessment

St.# 145 Street Name Main Street Type St Unit School Prog
City Groton Zip Code 01450

Owner Name: Friends of Prescott inc
Owner Address: 145 Main St #104 Groton Ma 01450
Contact Information:
Client Name (if different from owner):
Client Address:

Number of Rooms in Unit: 17
Property Type:
- [x] Single Family
- [ ] Multi Family # of Units:
- [ ] Condominium # of Units:
- [ ] Day Care [ ] Other: School Pro

Laundry in Basement? [ ] Yes [x] No
Finished Space in Basement? [ ] Yes [x] No
Possible Pb Water Service Line [ ] Yes [ ] No [x] Not Tested
Testing Method Used
Na_2S Expiration Date: / /
X-Ray Fluorescence
Model: RMD Serial # 2892

- [ ] Demarcation Lines
- [ ] Submitted for Compliance Evaluation

Key	Lead Column
COV	Covered
DC	Drop Ceiling
MET	Metal
MR	Metal Rep. Window
NA	Not Accessible
NC	No Coating
Tile	Tile (testing suggested)
VB	Vinyl Baseboard
VR	Vinyl Rep. Window

Key	Delead/IC Method Column	Key	Delead/IC Method Column
COV	Covered	REM	Removed
DIP	Dipped	REP	Replaced
ENC	Encapsulated	SCR	Scraped
INT	Intact	SFR	Storm Frame Removed
MI	Made Intact	SLD	Sealed
PRE	Prepared for Enc.	STP	Stripped
⧄	Component Does Not Exist	VR/MR	Vinyl/Metal Rep Window

Comments / Notes: * After School Program Areas only
** 2nd Cover Page Due To Add-ON Inspection

Floor# Bsmt (level within building of unit being inspected) Floor#





Property Diagram / Unit Labels



Pb (lead) equal to or greater than 1.0 mg/cm^2 with x-ray fluorescence or positive with Na_2S is **Dangerous.**

XRF Calibration Recorded in Log Book [x] ✓ - Check off when complete
Address Verified through USPS [x] ✓ - Check off when complete
Research on Lead Related History for Address [x] ✓ - Check off when complete
www.state.ma.us/dph/clppp or 800-532-9571

Joseph P Cataldo — Inspector's Name (print)
3147 — License #
Signature
6/ 13 /23 — Date

LI/RA - revised 06/17

Address: 145 MAIN ST. Apt# DAYCARE City GROTON

INSPECTION HISTORY

Determination / Lead Hazards?	Y / N	Inspector Name: ____, Lic# ____	Signature ____
Comprehensive Initial Inspection 0 8 2 7 1 8 / Lead Hazards?	Y / N	Inspector Name: M. BLACKMAN, Lic# 1377	Signature [signature]
Comp Initial w/Partial PCAD / Lead Hazards?	Y / N	Inspector Name: ____, Lic# ____	Signature ____
Addendum (add-on to Initial Inspection) 0 6 / 1 6 23 / Lead Hazards?	Y / N	Inspector Name: Joseph P Cobb, Lic# 3147	Signature [signature]
Addendum as Full Inspection / Lead Hazards?	Y / N	Inspector Name: ____, Lic# ____	Signature ____
Walk Through for Ed/Consultation 0 6 0 1 2 3		Inspector Name: Joseph P Cobb, Lic# 3147	Signature [signature]

REINSPECTION HISTORY

Visual Portion of Reocc. Reinspection	P / F	Inspector Name: ____, Lic# ____	Signature ____
Visual Portion of Reocc. Reinspection	P / F	Inspector Name: ____, Lic# ____	Signature ____
Dust Taken for Reocc. Reinspection	P / F	Inspector Name: ____, Lic# ____	Signature ____
Dust Taken for Reocc. Reinspection	P / F	Inspector Name: ____, Lic# ____	Signature ____
Visual Portion of Final Reinspection	P / F	Inspector Name: ____, Lic# ____	Signature ____
Visual Portion of Final Reinspection	P / F	Inspector Name: ____, Lic# ____	Signature ____
Dust Taken for Final Reinsp. (No Reocc)	P / F	Inspector Name: ____, Lic# ____	Signature ____
Dust Taken for Final Reinsp. (No Reocc)	P / F	Inspector Name: ____, Lic# ____	Signature ____

INTERIM CONTROL

Visual Risk Assessment / Urgent Pb. Hazards?	Y / N	R.A. Name: ____, Lic# ____	Signature ____
Dust Taken for Risk Assessment / Urgent Pb. Hazards?	Y / N	R.A. Name: ____, Lic# ____	Signature ____
Visual Portion of Reinspection for Interim Control	P / F	R.A. Name: ____, Lic# ____	Signature ____
Dust Taken for Risk Assessment Reinsp.	P / F	R.A. Name: ____, Lic# ____	Signature ____
Visual Portion of Reinspection for Interim Control	P / F	R.A. Name: ____, Lic# ____	Signature ____
Dust Taken for Risk Assessment Reinsp.	P / F	R.A. Name: ____, Lic# ____	Signature ____
Risk Assessment Recertification / Urgent Pb. Hazards?	Y / N	R.A. Name: ____, Lic# ____	Signature ____
Dust Taken for RA Recertification	P / F	R.A. Name: ____, Lic# ____	Signature ____

POST COMPLIANCE ASSESSMENT DETERMINATIONS

PCAD / Lead Hazards?	Y / N	Inspector Name: ____, Lic# ____	Signature ____
Full Inspection Acting as PCAD / Lead Hazards?	Y / N	Inspector Name: ____, Lic# ____	Signature ____
Visual Portion of PCAD Reinspection	P / F	Inspector Name: ____, Lic# ____	Signature ____
Dust Taken for PCAD Reinspection	P / F	Inspector Name: ____, Lic# ____	Signature ____
Dust Taken for PCAD Reinspection	P / F	Inspector Name: ____, Lic# ____	Signature ____

Address: 145 MAIN ST. Apt# DAYCARE City GROTON

REOCCUPANCY CERTIFICATE HISTORY

Certificate of Reoccupancy
Only after High/Mod Risk (# rooms rule)
Inspector Name:_____, Lic#_____
Signature_____

Certificate of Reoccupancy
Only after High/Mod Risk (# rooms rule)
Inspector Name:_____, Lic#_____
Signature_____

Certificate of Reoccupancy
Only after High/Mod Risk (# rooms rule)
Inspector Name:_____, Lic#_____
Signature_____

COMPLIANCE HISTORY

Letter of Full Initial Compliance
No prior history/ No signs of UD
Inspector Name:_____, Lic#_____
Signature_____

Letter of Interim Control
No prior Comp. Expires in 1 yr.
Inspector Name:_____, Lic#_____
Signature_____

Recertification of Interim Control
Expires 2 yrs from original Interim Control
Inspector Name:_____, Lic#_____
Signature_____

Letter of Full Deleading Compliance
Dust wipes if No Reocc.
Inspector Name:_____, Lic#_____
Signature_____

Certificate of Maintained Compliance
No Work = No Dust Work = 7 Dust
Inspector Name:_____, Lic#_____
Signature_____

Certificate of Restored Compliance
Dust wipes and auth. people
Inspector Name:_____, Lic#_____
Signature_____

COMPLIANCE HISTORY (CONT.)

Certificate of Maintained Compliance
No Work= No Dust Work = 7 Dust
Inspector Name:_____, Lic#_____
Signature_____

Certificate of Restored Compliance
Dust wipes and auth. people
Inspector Name:_____, Lic#_____
Signature_____

Certificate of Maintained Compliance
No Work = No Dust Work = 7 Dust
Inspector Name:_____, Lic#_____
Signature_____

Certificate of Restored Compliance
Dust wipes and auth. people
Inspector Name:_____, Lic#_____
Signature_____

OTHER HISTORY: WAIVERS/UD

Approved CLPPP Waiver
Attach to Comp Docs
Inspector Name:_____, Lic#_____
Signature_____

Approved CLPPP Waiver
Attach to Comp Docs
Inspector Name:_____, Lic#_____
Signature_____

UD / DES Visual Reinspection
No LOC Issued
P F
Inspector Name:_____, Lic#_____
Signature_____

UD / DES Dust Taken
No LOC Issued
P F
Inspector Name:_____, Lic#_____
Signature_____

UD / DES Dust Taken
No LOC Issued
P F
Inspector Name:_____, Lic#_____
Signature_____

UD / DES Final Reinspection
No LOC Issued
P F
Inspector Name:_____, Lic#_____
Signature_____

EXPLANATION OF LEAD INSPECTION / RISK ASSESSMENT REPORT FORM COLUMNS

This page provides general information needed to understand the lead inspection/risk assessment report. However, you should speak with the inspector/risk assessor before you start to do any work on your home.

SIDE Refers to A, B, C, or D side of the building or room. See the diagram on the cover sheet. The "A" side of the building or room is the side facing the street that gives the property its address (usually, it is the front of the building). Keeping your back to this street, from the "A" side move clockwise to the "B" side on your left, the "C" side opposite you, and the "D" side to the right. Numbering is from left to right.

LOCATION/ SURFACE Refers to the building component(s) being tested. Some surfaces may be made up of more than one part. For example, "Baseboard" may refer to four separate pieces of wood (one on each wall), but is still considered one surface.

LEAD The actual lead result. Each surface tested must have a result recorded in the "Lead" column.

- A number shows that the surface was tested with an XRF analyzer. A number equal to or greater than 1.0 mg/cm^2 is a dangerous level of lead.
- A "pos" or "neg" shows that the surface was tested with sodium sulfide. "Pos" means that there is a dangerous level of lead.
- "N/A" means that the inspector was not able to test the surface. The inspector must assume the surface contains lead and require it to be deleaded. Speak to the inspector about possible alternative testing options.
- "MET" or "MR" means that a metal surface was not tested. Metal handrails, metal window sills, and metal railing caps need to be deleaded if they test equal to or greater than 1.0 mg/cm^2, or are marked "MET" or "N/A". All other metal surfaces must be intact.
- For key to abbreviations like "COV", "VB", "VR" or "MR", "NC", "Tile", "DC", see the cover page.

TYPE OF HAZARD Not all lead paint must be deleaded. This column tells you IF and WHY a surface needs deleading. The deleading standards below may not apply for Interim Controls. Speak to your risk assessor for more information.

- "M/T" circled means that the surface is a moveable/impacted part of a window and must be deleaded in its entirety.
- "SF" circled indicates that there is a storm frame present which requires the blind stop and exterior sill be deleaded as interior moveable / impacted surfaces.
- "A/M" circled means that the surface is "accessible mouthable" and must be deleaded to a minimum of five feet high, four inches in from the edge or corner.
- "F" circled means that the surface is a "friction" surface and must be deleaded at all points of potential friction.
- "L" circled means that the surface is loose and must, at a minimum, be made intact. Loose leaded floors must be sealed with paint or similar coating and pass a dust wipe.
- If more than one choice is circled, the rules for deleading may change depending upon what method of deleading you choose. Speak to the inspector for more information.
- "N/A" means the inspector was unable to determine if the surface was a lead hazard. The person doing the deleading must check this surface and follow all the rules for deleading. Speak to the inspector for more information.
- If nothing is circled in the column, then it is likely the surface does not need deleading. Speak to the inspector for more information. Remember, this does not mean the entire surface is lead free, it just does not require deleading in its current condition.

URG HAZ? This column is completed during a risk assessment, which is an evaluation of a home's suitability for Interim Control. **Only a licensed risk assessor can do a risk assessment.** If "Y" is circled, then this surface is considered an "Urgent Lead Hazard" and deleading is required to qualify for Interim Control.

IC DATE The date the licensed risk assessor determines the surface meets the standards for Interim Control.

IC METH The deleading method or structural repair done to qualify the surface for Interim Control. Refer to the deleading codes key on the cover page.

DELEAD DATE The date that the lead inspector reinspects the surface and finds that it is in compliance.

DELEAD METH The method used to bring a surface into full compliance. Refer to codes in the Key on the report's cover page.

EXCLUDED SURFACES The amount of loose paint on a surface as measured by the lead inspector. "N/A" means that the inspector was not able to measure the loose paint, but has determined it is more than the cut-off for moderate risk making intact.

RULED OUT BOX Encapsulants only work well if the paint is in good condition. If the inspector sees that there are adhesion problems with eligible surfaces in a room, he/she will rule out encapsulation as a deleading method.

MEL BLACKMAN — Inspector (print) — M-1377 Lic # — Signature — 08- 27 - 2018 Date

MEL BLACKMAN — Risk Assessor (print) — R-1377 Lic # — Signature — / / Date

Address of Property: 145 MAIN ST. Apt # DAYCARE City: GROTON

ROOM # 1

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.3	L N/A	Y				
A B C D	Low Walls	0.8	L N/A	Y				
A B C D	Baseboards	0.2	L N/A	Y				
A B C D	Chair Rail	0.4	L N/A	Y				
A B C D	Radiator	0.6	L N/A	Y				
	Floor	Con	L ☐ (dust) N/A	Y				
	Ceiling	.	L N/A	Y				
A B	Door Shelves	0.0	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	0.1	L N/A	Y				
3 4	Door Jamb	0.1	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	0.1	L N/A	Y				
C D	Door Edge	0.1	F L N/A	Y				
1 2	Door Casing	0.3	L N/A	Y				
3 4	Door Jamb	0.0	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	0.2	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	0.1	L N/A	Y				
3 4	Door Jamb	0.0	F L N/A	Y				
	Threshold	/	L N/A	Y				
A	Closet Door		L N/A	Y				
B	Cl Door Edge	.	F L N/A	Y				
C	Cl Casing	.	L N/A	Y				
D	Closet Jamb		F L N/A	Y				
	Closet Walls		L N/A	Y				
1	Cl Baseboard	.	L N/A	Y				
2	Closet Pole	.	L N/A	Y				
3	Closet Shelf	.	L N/A	Y				
4	Cl Supports	.	L N/A	Y				
	Closet Floor	.	L ☐ (dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				
	Pipes	0.6	F Mi A/M L N/A	Y				
	Radiator	0.7	F Mi A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN)

LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
	Window Sill	0.0	Mi A/M L N/A	Y				
B	Win Apron	0.1	L N/A	Y				
C	Win Casing	0.3	L N/A	Y				
D	Header Stop	0.2	Mi L N/A	Y				
	Int Stops	0.2	Mi L N/A	Y				
	Win Int Sash	VR	Mi L N/A	Y				
2	Exterior Sill	VR	Mi SF L N/A	Y				
3	Part Bead	VR	Mi L N/A	Y				
4	Blind Stop	/	Mi SF L N/A	Y				
	Win Ext Sash	VR	Mi L N/A	Y				
	Window Sill	0.0	Mi A/M L N/A	Y				
B	Win Apron	0.1	L N/A	Y				
C	Win Casing	0.3	L N/A	Y				
D	Header Stop	0.4	Mi L N/A	Y				
	Int Stops	0.1	Mi L N/A	Y				
1	Win Int Sash	VR	Mi L N/A	Y				
2	Exterior Sill	VR	Mi SF L N/A	Y				
3	Part Bead	VR	Mi L N/A	Y				
4	Blind Stop	/	Mi SF L N/A	Y				
	Win Ext Sash	VR	Mi L N/A	Y				
	Window Sill	0.0	Mi A/M L N/A	Y				
B	Win Apron	0.0	L N/A	Y				
C	Win Casing	0.3	L N/A	Y				
D	Header Stop	0.4	Mi L N/A	Y				
	Int Stops	0.4	Mi L N/A	Y				
1	Win Int Sash	VR	Mi L N/A	Y				
2	Exterior Sill	VR	Mi SF L N/A	Y				
3	Part Bead	VR	Mi L N/A	Y				
4	Blind Stop	/	Mi SF L N/A	Y				
	Win Ext Sash	VR	Mi L N/A	Y				
A B	Door	0.4	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb		F L N/A	Y				
	Threshold		L N/A	Y				
A B	Fireplace		L N/A	Y				
C D	Mantel Trim	0.6	L N/A	Y				
A B C D	Win Above 5'	.	L N/A	Y				
	Ceiling Molding	.	L N/A	Y				
A B C D	Cl Drawers	.	L N/A	Y				
A B C D	Drawer Frame	.	L N/A	Y				
A B C D	Radiator Pipe	.	L N/A	Y				

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

MEL BLACKMAN	M-1377		08- 27 - 2018	Page 6 Of 28
Inspector (print)	Lic #	Signature	Date	
MEL BLACKMAN	R-1377		/ /	
Risk Assessor (print)	Lic #	Signature	Date	

Address of Property: 145 MAIN ST. Apt # DAYCARE City: GROTON

ROOM # 2

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	02	L N/A	Y				
A B C D	Low Walls	1.8	0 N/A	Y				
A B C D	Baseboards	0.3	L N/A	Y				
A B C D	Chair Rail	02	L N/A	Y				
A B	Radiator	12	0 N/A	Y				
	Floor	CW	L ☐(dust) N/A	Y				
	Ceiling	.	L N/A	Y				
A B	Door	00	L N/A	Y				
C D	Door Edge	0.1	F L N/A	Y				
1 2	Door Casing	03	L N/A	Y				
3 4	Door Jamb	00	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold		L N/A	Y				
A	Closet Door		L N/A	Y				
B	Cl Door Edge	.	F L N/A	Y				
C	Cl Casing	.	L N/A	Y				
D	Closet Jamb	.	F L N/A	Y				
	Closet Walls	.	L N/A	Y				
1	Cl Baseboard	.	L N/A	Y				
2	Closet Pole	.	L N/A	Y				
3	Closet Shelf	.	L N/A	Y				
4	Cl Supports	.	L N/A	Y				
	Closet Floor	.	L ☐(dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				
	Pipes	.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN)

LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	00	M/I A/M L N/A	Y				
B	Win Apron	04	L N/A	Y				
C	Win Casing	02	L N/A	Y				
D	Header Stop	00	M/I L N/A	Y				
	Int Stops	00	M/I L N/A	Y				
1	Win Int Sash	VR	M/I L N/A	Y				
2	Exterior Sill	VR	M/I SF L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash		M/I L N/A	Y				
2	Exterior Sill		M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B	Fireplace	.	L N/A	Y				
C D	Mantle	.	L N/A	Y				
A B C D	Win Above 5'	.	L N/A	Y				
	Ceiling Molding	.	L N/A	Y				
A B C D	Cl Drawers	.	L N/A	Y				
A B C D	Drawer Frame	.	L N/A	Y				
A B C D	Radiator Pipe	.	L N/A	Y				

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

MEL BLACKMAN — M-1377 — Signature — 08- 27 - 2018
Inspector (print) — Lic # — Date

MEL BLACKMAN — R-1377 — / /
Risk Assessor (print) — Lic # — Signature — Date

Address of Property: 145 MAIN ST. Apt # DAYCARE City: GROTON

ROOM # 3

Page 8 Of 40

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.4	L N/A	Y				
A B C D	Low Walls	0.4	L N/A	Y				
A B C D	Baseboards	0.1	L N/A	Y				
A B C D	Chair Rail	0.3	L N/A	Y				
	Radiator	0.8	L N/A	Y				
	Floor	CN	L ☐(dust) N/A	Y				
	Ceiling	DC	L N/A	Y				
A B	Door	01	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	0.4	L N/A	Y				
3 4	Door Jamb	0.3	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	0.0	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	01	L N/A	Y				
3 4	Door Jamb	0.3	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	0.0	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	01	L N/A	Y				
3 4	Door Jamb	0.3	F L N/A	Y				
	Threshold	/	L N/A	Y				
A	Closet Door	0.0	L N/A	Y				
B	Cl Door Edge	/	F L N/A	Y				
C	Cl Casing	0.3	L N/A	Y				
D	Closet Jamb	0.4	F L N/A	Y				
	Closet Walls	0.5	L N/A	Y				
1	Cl Baseboard	0.3	L N/A	Y				
2	Closet Pole	/	L N/A	Y				
3	Closet Shelf	0.0	L N/A	Y				
4	Cl Supports	0.3	L N/A	Y				
	Closet Floor	0.1	L ☐(dust) N/A	Y				
	Closet Ceiling	MA	L N/A	Y				
	Pipes Stacks	01	F M/I A/M L N/A	Y				
	Column	0.3	F M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN)

LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	0.0	M/I A/M L N/A	Y				
B	Win Apron	0.3	L N/A	Y				
C	Win Casing	0.3	L N/A	Y				
D	Header Stop	0.4	M/I L N/A	Y				
	Int Stops	02	M/I L N/A	Y				
1	Win Int Sash	ML	M/I L N/A	Y				
2	Exterior Sill	ML	M/I SF L N/A	Y				
3	Part Bead	ML	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	ML	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop		M/I L N/A	Y				
	Int Stops		M/I L N/A	Y				
1	Win Int Sash		M/I L N/A	Y				
2	Exterior Sill		M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A B	Door	01	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	01	L N/A	Y				
3 4	Door Jamb	0.3	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Fireplace	.	L N/A	Y				
C D	Mantle	.	L N/A	Y				
A B C D	Win Above 5'	.	L N/A	Y				
	Ceiling Molding		L N/A	Y				
A B C D	Cl Drawers	.	L N/A	Y				
A B C D	Drawer Frame	.	L N/A	Y				
A B C D	Radiator Pipe	.	L N/A	Y				

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

MEL BLACKMAN — M-1377 — Signature — 08-27-2018
Inspector (print) — Lic # — Date

MEL BLACKMAN — R-1377 — / /
Risk Assessor (print) — Lic # — Signature — Date

Address of Property: 145 MAIN ST. Apt # DAYCARE City: GROTON

ROOM # 4

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.2	L N/A	Y				
A B C D	Low Walls	0.4	L N/A	Y				
A B C D	Baseboards	0.0	L N/A	Y				
A B C D	Chair Rail	0.2	L N/A	Y				
A B C D	Radiator	0.3	L N/A	Y				
	Floor	CN	L ☐ (dust) N/A	Y				
	Ceiling	0.2	L N/A	Y				
A B	Door	0.0	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	0.2	L N/A	Y				
3 4	Door Jamb	0.0	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	0.0	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	0.3	L N/A	Y				
3 4	Door Jamb	0.0	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	0.2	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	0.2	L N/A	Y				
3 4	Door Jamb	0.0	F L N/A	Y				
	Threshold	/	L N/A	Y				
A	Closet Door	.	L N/A	Y				
B	Cl Door Edge	.	F L N/A	Y				
C	Cl Casing	.	L N/A	Y				
D	Closet Jamb	.	F L N/A	Y				
	Closet Walls	.	L N/A	Y				
1	Cl Baseboard	.	L N/A	Y				
2	Closet Pole	.	L N/A	Y				
3	Closet Shelf	.	L N/A	Y				
4	Cl Supports	.	L N/A	Y				
	Closet Floor	.	L ☐ (dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				
	Floor Win Bars	0.5	F M/A/M L N/A	Y				
	Door Frame	0.3	F M/A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	0.0	M/I A/M L N/A	Y				
B	Win Apron	0.0	L N/A	Y				
C	Win Casing	0.3	L N/A	Y				
D	Header Stop	0.4	M/I L N/A	Y				
	Int Stops	0.1	M/I L N/A	Y				
1	Win Int Sash	VM	M/I L N/A	Y				
2	Exterior Sill	VM	M/I SF L N/A	Y				
3	Part Bead	VM	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	VM	M/I L N/A	Y				
A	Window Sill	0.2	M/I A/M L N/A	Y				
B	Win Apron	0.1	L N/A	Y				
C	Win Casing	0.2	L N/A	Y				
D	Header Stop	0.3	M/I L N/A	Y				
	Int Stops	0.0	M/I L N/A	Y				
1	Win Int Sash	VM	M/I L N/A	Y				
2	Exterior Sill	VM	M/I SF L N/A	Y				
3	Part Bead	VM	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	VM	M/I L N/A	Y				
A	Window Sill	0.0	M/I A/M L N/A	Y				
B	Win Apron	0.0	L N/A	Y				
C	Win Casing	0.2	L N/A	Y				
D	Header Stop	0.4	M/I L N/A	Y				
	Int Stops	0.4	M/I L N/A	Y				
1	Win Int Sash	VM	M/I L N/A	Y				
2	Exterior Sill	VM	M/I SF L N/A	Y				
3	Part Bead	VM	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	VM	M/I L N/A	Y				
A B	Door Frame	0.2	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	0.2	L N/A	Y				
3 4	Door Jamb	/	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B	Fireplace Trim	0.0	L N/A	Y				
C D	Mantle Shelves	0.0	L N/A	Y				
A B C D	Win Above 5'	.	L N/A	Y				
	Ceiling Molding	.	L N/A	Y				
A B C D	Cl Drawers	.	L N/A	Y				
A B C D	Drawer Frame	.	L N/A	Y				
A B C D	Radiator Pipe	.	L N/A	Y				

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

MEL BLACKMAN — Inspector (print) — Lic # M-1377 — Signature — Date 08- 27 - 2018

MEL BLACKMAN — Risk Assessor (print) — Lic # R-1377 — Signature — Date / /

Page 9 Of 38

10 40

Address of Property: 145 MAIN ST. Apt # DAYCARE City: GROTON

ROOM # 5

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	03	L N/A	Y				
A B C D	Low Walls	04	L N/A	Y				
A B C D	Baseboards	02	L N/A	Y				
A B C D	Chair Rail	02	L N/A	Y				
A B C D	Radiator	06	L N/A	Y				
	Floor	CW	L ☐(dust) N/A	Y				
	Ceiling	DC	L N/A	Y				
A B	Door	00	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	03	L N/A	Y				
3 4	Door Jamb	00	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	00	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	04	L N/A	Y				
3 4	Door Jamb	03	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	03	L N/A	Y				
	Door Edge	.	F L N/A	Y				
	Door Casing	00	L N/A	Y				
3 4	Door Jamb	00	F L N/A	Y				
	Threshold	/	L N/A	Y				
A	Closet Door	00	L N/A	Y				
B	Cl Door Edge	02	F L N/A	Y				
C	Cl Casing	00	L N/A	Y				
D	Closet Jamb	00	F L N/A	Y				
	Closet Walls	03	L N/A	Y				
1	Cl Baseboard	00	L N/A	Y				
2	Closet Pole	/	L N/A	Y				
3	Closet Shelf	02	L N/A	Y				
4	Cl Supports	00	L N/A	Y				
	Closet Floor	00	L ☐(dust) N/A	Y				
	Closet Ceiling	03	L N/A	Y				
	Baseboard Lines	02	F M/A/M L N/A	Y				
		/	F M/A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN)

LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	09	M/ A/M L N/A	Y				
B	Win Apron	00	L N/A	Y				
C	Win Casing	02	L N/A	Y				
D	Header Stop	00	M/ L N/A	Y				
	Int Stops	02	M/ L N/A	Y				
1	Win Int Sash	M	M/ L N/A	Y				
2	Exterior Sill	M	M/ SF L N/A	Y				
3	Part Bead	M	M/ L N/A	Y				
4	Blind Stop	/	M/ SF L N/A	Y				
	Win Ext Sash	M	M/ L N/A	Y				
A	Window Sill	00	M/ A/M L N/A	Y				
B	Win Apron	03	L N/A	Y				
C	Win Casing	04	L N/A	Y				
D	Header Stop	03	M/ L N/A	Y				
	Int Stops	02	M/ L N/A	Y				
1	Win Int Sash	M	M/ L N/A	Y				
2	Exterior Sill	.	M/ SF L N/A	Y				
3	Part Bead	.	M/ L N/A	Y				
4	Blind Stop	/	M/ SF L N/A	Y				
	Win Ext Sash	.	M/ L N/A	Y				
A	Window Sill	.	M/ A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/ L N/A	Y				
	Int Stops	.	M/ L N/A	Y				
1	Win Int Sash	.	M/ L N/A	Y				
2	Exterior Sill	/	M/ SF L N/A	Y				
3	Part Bead	.	M/ L N/A	Y				
4	Blind Stop	.	M/ SF L N/A	Y				
	Win Ext Sash	.	M/ L N/A	Y				
A B	Door	03	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	00	L N/A	Y				
3 4	Door Jamb	00	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Fireplace	.	L N/A	Y				
C D	Mantle	/	L N/A	Y				
A B C D	Win Above 5'	/	L N/A	Y				
	Ceiling Molding	.	L N/A	Y				
A B C D	Cl Drawers	.	L N/A	Y				
A B C D	Drawer Frame	.	L N/A	Y				
A B C D	Radiator Pipe	.	L N/A	Y				

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

MEL BLACKMAN — M-1377 — Signature — 08- 27 - 2018
Inspector (print) — Lic # — Date

MEL BLACKMAN — R-1377 — / /
Risk Assessor (print) — Lic # — Signature — Date

Address of Property: 145 MAIN ST. Apt # DAYCARE City: GROTON

ROOM # 6

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	03	L N/A	Y				
A B C D	Low Walls	05	L N/A	Y				
A B C D	Baseboards	00	L N/A	Y				
A B C D	Chair Rail	04	L N/A	Y				
A B	Radiator	02	L N/A	Y				
	Floor	CN	L ☐(dust) N/A	Y				
	Ceiling	DC	L N/A	Y				
A B	Door	01	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	02	L N/A	Y				
3 4	Door Jamb	00	F L N/A	Y				
	Threshold	02	L N/A	Y				
A B	Door	00	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	01	L N/A	Y				
3 4	Door Jamb	00	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	01	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	04	L N/A	Y				
3 4	Door Jamb	04	F L N/A	Y				
	Threshold	/	L N/A	Y				
A	Closet Door	.	L N/A	Y				
B	Cl Door Edge	.	F L N/A	Y				
C	Cl Casing	.	L N/A	Y				
D	Closet Jamb	.	F L N/A	Y				
	Closet Walls	.	L N/A	Y				
1	Cl Baseboard	.	L N/A	Y				
2	Closet Pole		L N/A	Y				
3	Closet Shelf	.	L N/A	Y				
4	Cl Supports	.	L N/A	Y				
	Closet Floor	.	L ☐(dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				
	Pipes/Duct (Pipe 02)		F M/ A/M L N/A	Y				
A	Wall Casing	04	F M/ A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	03	M/ A/M L N/A	Y				
B	Win Apron	00	L N/A	Y				
C	Win Casing	02	L N/A	Y				
D	Header Stop	02	M/ L N/A	Y				
	Int Stops	02	M/ L N/A	Y				
1	Win Int Sash	M	M/ L N/A	Y				
2	Exterior Sill	M	M/ SF L N/A	Y				
3	Part Bead	M	M/ L N/A	Y				
4	Blind Stop	/	M/ SF L N/A	Y				
	Win Ext Sash	M	M/ L N/A	Y				
A	Window Sill	.	M/ A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/ L N/A	Y				
	Int Stops	.	M/ L N/A	Y				
1	Win Int Sash	.	M/ L N/A	Y				
2	Exterior Sill	.	M/ SF L N/A	Y				
3	Part Bead		M/ L N/A	Y				
4	Blind Stop	.	M/ SF L N/A	Y				
	Win Ext Sash	.	M/ L N/A	Y				
A	Window Sill	.	M/ A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/ L N/A	Y				
	Int Stops	.	M/ L N/A	Y				
1	Win Int Sash	.	M/ L N/A	Y				
2	Exterior Sill	.	M/ SF L N/A	Y				
3	Part Bead	.	M/ L N/A	Y				
4	Blind Stop	.	M/ SF L N/A	Y				
	Win Ext Sash	.	M/ L N/A	Y				
A B	Door	01	L N/A	Y				
C D	Door Edge	03	F L N/A	Y				
1 2	Door Casing	00	L N/A	Y				
3 4	Door Jamb	04	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Fireplace	.	L N/A	Y				
C D	Mantle	.	L N/A	Y				
A B C D	Win Above 5'	.	L N/A	Y				
	Ceiling Molding		L N/A	Y				
A B C D	Cl Drawers		L N/A	Y				
A B C D	Drawer Frame		L N/A	Y				
A B C D	Radiator Pipe		L N/A	Y				

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

MEL BLACKMAN — Inspector (print) | M-1377 — Lic # | Signature | 08- 27 - 2018 — Date

MEL BLACKMAN — Risk Assessor (print) | R-1377 — Lic # | Signature | / / — Date

Address of Property: 145 MAIN ST. Apt # DAYCARE City: GROTON

ROOM # 7

Page 14 Of 38

12 40

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	04	L N/A	Y				
A B C D	Low Walls	02	L N/A	Y				
A B C D	Baseboards	01	L N/A	Y				
A B C D	Chair Rail	00	L N/A	Y				
A B C D	Radiator	21	N/A	Y				
	Floor	C00	L ☐(dust) N/A	Y				
	Ceiling	DC	L N/A	Y				
A B	Door	00	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	01	L N/A	Y				
3 4	Door Jamb	03	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B	Door	03	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	03	L N/A	Y				
3 4	Door Jamb	03	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	03	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	01	L N/A	Y				
3 4	Door Jamb	00	F L N/A	Y				
	Threshold	/	L N/A	Y				
A	Closet Door	.	L N/A	Y				
B	Cl Door Edge	.	F L N/A	Y				
C	Cl Casing	.	L N/A	Y				
D	Closet Jamb	.	F L N/A	Y				
	Closet Walls	.	L N/A	Y				
1	Cl Baseboard	.	L N/A	Y				
2	Closet Pole	.	L N/A	Y				
3	Closet Shelf	.	L N/A	Y				
4	Cl Supports	.	L N/A	Y				
	Closet Floor	.	L ☐(dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				
	Pipes	.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN)

LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	00	M/I A/M L N/A	Y				
B	Win Apron	03	L N/A	Y				
C	Win Casing	00	L N/A	Y				
D	Header Stop	00	M/I L N/A	Y				
	Int Stops	01	M/I L N/A	Y				
1	Win Int Sash	M	M/I L N/A	Y				
2	Exterior Sill	M	M/I SF L N/A	Y				
3	Part Bead	M	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	M	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B	Fireplace	.	L N/A	Y				
C D	Mantle	.	L N/A	Y				
A B C D	Win Above 5'	.	L N/A	Y				
	Ceiling Molding	.	L N/A	Y				
A B C D	Cl Drawers	.	L N/A	Y				
A B C D	Drawer Frame	.	L N/A	Y				
A B C D	Radiator Pipe	.	L N/A	Y				

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

MEL BLACKMAN — Inspector (print) — M-1377 Lic # — Signature — 08- 27 - 2018 Date

MEL BLACKMAN — Risk Assessor (print) — R-1377 Lic # — Signature — / / Date

Address of Property: 145 MAIN ST. Apt # DAYCARE City: GROTON

ROOM # 8 GYMNASIUM (1 of 2)

Page 13 of 40

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	04	L N/A	Y				
A B C D	Low Walls	02	L N/A	Y				
A B C D	Baseboards	00	L N/A	Y				
A B C D	Chair Rail	03	L N/A	Y				
A B C D	Radiator	/	L N/A	Y				
	Floor	00	L ☐(dust) N/A	Y				
	Ceiling	04	L N/A	Y				
1 2 B	Door	00	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	01	L N/A	Y				
3 4	Door Jamb	02	F L N/A	Y				
	Threshold	/	L N/A	Y				
1 2 B	Door	00	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	04	L N/A	Y				
3 4	Door Jamb	01	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door *	01	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	04	L N/A	Y				
3 4	Door Jamb	02	F L N/A	Y				
1	Threshold	/	L N/A	Y				
A	Closet Door	.	L N/A	Y				
B	Cl Door Edge	.	F L N/A	Y				
C	Cl Casing	.	L N/A	Y				
D	Closet Jamb	.	F L N/A	Y				
	Closet Walls	.	L N/A	Y				
1	Cl Baseboard	.	L N/A	Y				
2	Closet Pole	.	L N/A	Y				
3	Closet Shelf	.	L N/A	Y				
4	Cl Supports	.	L N/A	Y				
	Closet Floor	.	L ☐(dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				
	Pipes	.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

* to Storage rm. - locked

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A	Window Sill		M/I A/M L N/A	Y				
B	Win Apron		L N/A	Y				
C	Win Casing		L N/A	Y				
D	Header Stop		M/I L N/A	Y				
	Int Stops		M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A B	Door	/	L N/A	Y				
C	Door Edge	.	F L N/A	Y				
1 2	Door Casing	04	L N/A	Y				
3 4	Door Jamb	01	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Fireplace	.	L N/A	Y				
C D	Mantle	.	L N/A	Y				
A B C D	Win Above 5'		L N/A	Y				
	Ceiling Molding		L N/A	Y				
A B C D	Cl Drawers	.	L N/A	Y				
A B C D	Drawer Frame	.	L N/A	Y				
A B C D	Radiator Pipe	.	L N/A	Y				

☐ *Check the box if this ROOM is RULED OUT for encapsulation* because there are 3 or more A/M surfaces with adhesion problems

MEL BLACKMAN — M-1377 — Signature — 08- 27 - 2018
Inspector (print) — Lic # — Date

MEL BLACKMAN — R-1377 — / /
Risk Assessor (print) — Lic # — Signature — Date

Address of Property: 145 MAIN ST. Apt # DAYCARE City: GROTON

ROOM # 8 (2nd)

Page 13 Of 28 — 14 40

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	.	L N/A	Y				
A B C D	Low Walls	.	L N/A	Y				
A B C D	Baseboards	.	L N/A	Y				
A B C D	Chair Rail	.	L N/A	Y				
A B C D	Radiator	.	L N/A	Y				
	Floor	.	L ☐(dust) N/A	Y				
	Ceiling	.	L N/A	Y				
A B C	Door	00	L N/A	Y				
	Door Edge	/	F L N/A	Y				
1 2	Door Casing	03	L N/A	Y				
3 4	Door Jamb	0.1	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B C	Door	02	L N/A	Y				
	Door Edge	.	F L N/A	Y				
1 2	Door Casing	01	L N/A	Y				
3 4	Door Jamb	00	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	01	L N/A	Y				
	Door Edge	/	F L N/A	Y				
	Door Casing	02	L N/A	Y				
3 4	Door Jamb	00	F L N/A	Y				
	Threshold	/	L N/A	Y				
A	Closet Door	00	L N/A	Y				
B	Cl Door Edge	/	F L N/A	Y				
C	Cl Casing	04	L N/A	Y				
	Closet Jamb	01	F L N/A	Y				
	Closet Walls	0.7	L N/A	Y				
1	Cl Baseboard	00	L N/A	Y				
2	Closet Pole	/	L N/A	Y				
3	Closet Shelf	NC	L N/A	Y				
4	Cl Supports	NC	L N/A	Y				
	Closet Floor	0.0	L ☐(dust) N/A	Y				
	Closet Ceiling	NA	L N/A	Y				
	Pipes	/	F M/I A/M L N/A	Y				
	Sidelights	0.1	F M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN)

LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	00	M/I A/M L N/A	Y				
B	Win Apron	01	L N/A	Y				
C	Win Casing	01	L N/A	Y				
D	Header Stop	02	M/I L N/A	Y				
	Int Stops	00	M/I L N/A	Y				
1	Win Int Sash	VR	M/I L N/A	Y				
2	Exterior Sill	CW	M/I SF L N/A	Y				
3	Part Bead	CW	M/I L N/A	Y				
4	Blind Stop	CW	M/I SF L N/A	Y				
	Win Ext Sash	CW	M/I L N/A	Y				
A	Window Sill	0.0	M/I A/M L N/A	Y				
B	Win Apron	0.0	L N/A	Y				
C	Win Casing	0.3	L N/A	Y				
D	Header Stop	03	M/I L N/A	Y				
	Int Stops	0.0	M/I L N/A	Y				
1	Win Int Sash	VR	M/I L N/A	Y				
2	Exterior Sill	CW	M/I SF L N/A	Y				
3	Part Bead	CW	M/I L N/A	Y				
4	Blind Stop	CW	M/I SF L N/A	Y				
	Win Ext Sash	CW	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A B	Door	00	L N/A	Y				
D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	01	L N/A	Y				
3 4	Door Jamb	02	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Fireplace	/	L N/A	Y				
C D	Mantle	.	L N/A	Y				
A B	Win Above 5'	VR	L N/A	Y				
	Ceiling Molding	.	L N/A	Y				
A B C D	Cl Drawers	.	L N/A	Y				
A B C D	Drawer Frame	.	L N/A	Y				
A B C D	Radiator Pipe	.	L N/A	Y				

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

MEL BLACKMAN — M-1377 — Signature — 08- 27 - 2018
Inspector (print) — Lic # — Date

MEL BLACKMAN — R-1377 — / /
Risk Assessor (print) — Lic # — Signature — Date

Address of Property: 145 MAIN ST. Apt # DAYCARE City: GROTON

ROOM # 9

Page 14 of 28
15 40

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.3	L N/A	Y				
A B C D	Low Walls	0.4	L N/A	Y				
A B C D	Baseboards	0.1	L N/A	Y				
A B C D	Chair Rail	0.2	L N/A	Y				
A B C D	Radiator	0.6	L N/A	Y				
	Floor	CPV	L ☐ (dust) N/A	Y				
	Ceiling	0.3	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	0.1	L N/A	Y				
3 4	Door Jamb	0.3	F L N/A	Y				
	Threshold		L N/A	Y				
A B	Door	0.0	L N/A	Y				
C D	Door Edge		F L N/A	Y				
1 2	Door Casing	0.0	L N/A	Y				
3 4	Door Jamb	0.2	F L N/A	Y				
	Threshold		L N/A	Y				
A B	Door	0.2	L N/A	Y				
C D	Door Edge		F L N/A	Y				
1 2	Door Casing	0.0	L N/A	Y				
3 4	Door Jamb	0.2	F L N/A	Y				
	Threshold		L N/A	Y				
A	Closet Door	.	L N/A	Y				
B	Cl Door Edge	.	F L N/A	Y				
C	Cl Casing	.	L N/A	Y				
D	Closet Jamb	.	F L N/A	Y				
	Closet Walls	.	L N/A	Y				
1	Cl Baseboard	.	L N/A	Y				
2	Closet Pole		L N/A	Y				
3	Closet Shelf		L N/A	Y				
4	Cl Supports	.	L N/A	Y				
	Closet Floor	.	L ☐ (dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				
	~~Floor~~	.	F M/I A/M L N/A	Y				
	Board from	0.3	F M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	0.3	M/I A/M L N/A	Y				
B	Win Apron	0.1	L N/A	Y				
C	Win Casing	0.0	L N/A	Y				
D	Header Stop	0.4	M/I L N/A	Y				
	Int Stops	0.2	M/I L N/A	Y				
1	Win Int Sash	VR	M/I L N/A	Y				
2	Exterior Sill	VR	M/I SF L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B	Fireplace	.	L N/A	Y				
C D	Mantle	.	L N/A	Y				
A B C D	Win Above 5'	.	L N/A	Y				
	Ceiling Molding	.	L N/A	Y				
A B C D	Cl Drawers	.	L N/A	Y				
A B C D	Drawer Frame	.	L N/A	Y				
A B C D	Radiator Pipe	.	L N/A	Y				

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

MEL BLACKMAN — M-1377 — Signature — 08- 27 - 2018

Inspector (print) — Lic # — Signature — Date

MEL BLACKMAN — R-1377 — / /

Risk Assessor (print) — Lic # — Signature — Date

Address of Property: 145 MAIN ST. Apt # DAYCARE City: GROTON

ROOM # 10

Page 16 of 40

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.4	L N/A	Y				
A B C D	Low Walls	0.1	L N/A	Y				
A B C D	Baseboards	0.0	L N/A	Y				
A B C D	Chair Rail	0.3	L N/A	Y				
A B C D	Radiator	0.5	L N/A	Y				
	Floor	CN	L ☐(dust) N/A	Y				
	Ceiling	DC	L N/A	Y				
A B	Door	0.0	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	0.2	L N/A	Y				
3 4	Door Jamb	0.2	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	0.1	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	0.1	L N/A	Y				
3 4	Door Jamb	0.0	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	/	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
	Door Casing	/	L N/A	Y				
3 4	Door Jamb	/	F L N/A	Y				
	Threshold	/	L N/A	Y				
A	Closet Door	/	L N/A	Y				
B	Cl Door Edge	/	F L N/A	Y				
C	Cl Casing	/	L N/A	Y				
D	Closet Jamb	/	F L N/A	Y				
	Closet Walls	/	L N/A	Y				
1	Cl Baseboard	/	L N/A	Y				
2	Closet Pole	/	L N/A	Y				
3	Closet Shelf	/	L N/A	Y				
4	Cl Supports	/	L N/A	Y				
	Closet Floor	/	L ☐(dust) N/A	Y				
	Closet Ceiling	/	L N/A	Y				
	Pipes	/	F M/I A/M L N/A	Y				
		/	F M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	0.3	M/I A/M L N/A	Y				
B	Win Apron	0.0	L N/A	Y				
C	Win Casing	0.2	L N/A	Y				
D	Header Stop	0.0	M/I L N/A	Y				
	Int Stops	0.0	M/I L N/A	Y				
1	Win Int Sash	VR	M/I L N/A	Y				
2	Exterior Sill	VR	M/I SF L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				
A	Window Sill	/	M/I A/M L N/A	Y				
B	Win Apron	/	L N/A	Y				
C	Win Casing	/	L N/A	Y				
D	Header Stop	/	M/I L N/A	Y				
	Int Stops	/	M/I L N/A	Y				
1	Win Int Sash	/	M/I L N/A	Y				
2	Exterior Sill	/	M/I SF L N/A	Y				
3	Part Bead	/	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	/	M/I L N/A	Y				
A	Window Sill	/	M/I A/M L N/A	Y				
B	Win Apron	/	L N/A	Y				
C	Win Casing	/	L N/A	Y				
D	Header Stop	/	M/I L N/A	Y				
	Int Stops	/	M/I L N/A	Y				
1	Win Int Sash	/	M/I L N/A	Y				
2	Exterior Sill	/	M/I SF L N/A	Y				
3	Part Bead	/	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	/	M/I L N/A	Y				
A B	Door	/	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	/	L N/A	Y				
3 4	Door Jamb	/	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Fireplace	/	L N/A	Y				
C D	Mantle	/	L N/A	Y				
A B C D	Win Above 5'	/	L N/A	Y				
	Ceiling Molding	/	L N/A	Y				
A B C D	Cl Drawers	/	L N/A	Y				
A B C D	Drawer Frame	/	L N/A	Y				
A B C D	Radiator Pipe	/	L N/A	Y				

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

Joseph P Cataldo — Inspector (print) | 3147 — Lic # | Signature | 6 16 23 — Date | Page 12 of 14

Risk Assessor (print) | Lic # | Signature | Date

Address of Property: 145 Main St | Apt. # None | City: Groton 01450

ROOM # 11 Lot 2

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.1	L N/A	Y				
A B C D	Low Walls	02	L N/A	Y				
A B C D	Baseboards	VR	L N/A	Y				
A B C D	Chair Rail	/	L N/A	Y				
A B C D	Radiator	/	L N/A	Y				
	Floor	02	L ☐ (dust) N/A	Y				
	Ceiling	0.1	L N/A	Y				
A B	Door (2)	0.1	L N/A	Y	Side	Lates		
C D	Door Edge	0.1	F L N/A	Y	0.4			
1 2	Door Casing	0.1	L N/A	Y				
3 4	Door Jamb	0.1	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door (2)	0.4	L N/A	Y				
C D	Door Edge	0.3	F L N/A	Y				
1 2	Door Casing	00	L N/A	Y				
3 4	Door Jamb	00	F L N/A	Y				
	Threshold	NC	L N/A	Y				
A B	Door	0.1	L N/A	Y				
C D	Door Edge	N/A	F L N/A	Y				
1 2	Door Casing	0.1	L N/A	Y				
3 4	Door Jamb	N/A	F L N/A	Y				
	Threshold	/	L N/A	Y				
	Closet Door	.	L N/A	Y				
A	Cl Door Edge	.	F L N/A	Y				
B	Cl Casing	.	L N/A	Y				
C	Closet Jamb		F L N/A	Y				
D	Closet Walls		L N/A	Y				
	Cl Baseboard		L N/A	Y				
1	Closet Pole		L N/A	Y				
2	Closet Shelf		L N/A	Y				
3	Cl Supports		L N/A	Y				
4	Closet Floor		L ☐ (dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN.)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	0.1	M/I A/M L N/A	Y				
B	Win Apron	0.1	L N/A	Y				
C	Win Casing	02	L N/A	Y				
D	Header Stop	0.1	M/I L N/A	Y				
	Int Stops	0.1	M/I L N/A	Y				
1	Win Int Sash	VR	M/I L N/A	Y				
2	Exterior Sill	VR	M/I SF L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				
A	Window Sill	0.1	M/I A/M L N/A	Y				
B	Win Apron	02	L N/A	Y				
C	Win Casing	0.1	L N/A	Y				
D	Header Stop	0.1	M/I L N/A	Y				
	Int Stops	02	M/I L N/A	Y				
1	Win Int Sash	VR	M/I L N/A	Y				
2	Exterior Sill	VR	M/I SF L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				
A	Window Sill	01	M/I A/M L N/A	Y				
B	Win Apron	02	L N/A	Y				
C	Win Casing	01	L N/A	Y				
D	Header Stop	01	M/I L N/A	Y				
	Int Stops	02	M/I L N/A	Y				
1	Win Int Sash	01	M/I L N/A	Y				
2	Exterior Sill	N/A	M/I SF L N/A	Y				
3	Part Bead	N/A	M/I L N/A	Y				
4	Blind Stop	N/A	M/I SF L N/A	Y				
	Win Ext Sash	N/A	M/I L N/A	Y				
A B	Fireplace	.	L N/A	Y				
C D	Mantle		L N/A	Y				
A B C D	Win Above 5'	.	L N/A	Y				
	Ceiling Molding	.	L N/A	Y				
	Knee Wall	0.1	F M/I A/M L N/A	Y				
	Knee Wall	.	F M/I A/M L N/A	Y				
	Top Cap	0.1	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

Joseph P Cataldo | 3147 | [signature] | 6/16/23 | Page 18 of 40
Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic # | Signature | Date

Address of Property: 145 Main St | Apt. # None | City: Groton 01450

CONTINUATION OF ROOM (11) 2 of 7

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	0.1	M/I A/M L N/A	Y				
B	Win Apron	0.1	L N/A	Y				
C	Win Casing	0.2	L N/A	Y				
D	Header Stop	0.1	M/I L N/A	Y				
	Int Stops	0.0	M/I L N/A	Y				
#	Win Int Sash	0.1	M/I L N/A	Y				
	Exterior Sill	/	M/I SF L N/A	Y				
	Part Bead	/	M/I L N/A	Y				
	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	0.1	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
#	Win Int Sash	.	M/I L N/A	Y				
	Exterior Sill	.	M/I SF L N/A	Y				
	Part Bead	.	M/I L N/A	Y				
	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
#	Win Int Sash	.	M/I L N/A	Y				
	Exterior Sill	.	M/I SF L N/A	Y				
	Part Bead	.	M/I L N/A	Y				
	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN.)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
#	Win Int Sash	.	M/I L N/A	Y				
	Exterior Sill	.	M/I SF L N/A	Y				
	Part Bead	.	M/I L N/A	Y				
	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
#	Win Int Sash	.	M/I L N/A	Y				
	Exterior Sill	.	M/I SF L N/A	Y				
	Part Bead	.	M/I L N/A	Y				
	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
#	Win Int Sash	.	M/I L N/A	Y				
	Exterior Sill	.	M/I SF L N/A	Y				
	Part Bead	.	M/I L N/A	Y				
	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are3 or more A/M surfaces with adhesion problems

Joseph P Cataldo — Inspector (print) | 3147 — Lic # | Signature | 6 16 23 — Date | Page 19 of 40

Risk Assessor (print) | Lic # | Signature | Date

Address of Property: 145 Main St | Apt. # None | City: Groton 01450

ROOM # 12

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.4	L N/A	Y				
A B C D	Low Walls	/	L N/A	Y				
A B C D	Baseboards	VB	L N/A	Y				
A B C D	Chair Rail	/	L N/A	Y				
A B C D	Radiator	/	L N/A	Y				
	Floor	Cov	L ☐ (dust) N/A	Y				
	Ceiling	0.1	L N/A	Y				
A B	Door	0.1	L N/A	Y				
C D	Door Edge	N/A	F L N/A	Y				
1 2	Door Casing	0.1	L N/A	Y				
3 4	Door Jamb	N/A	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	0.1	L N/A	Y				
C D	Door Edge	0.2	F L N/A	Y				
1 2	Door Casing	0.1	L N/A	Y				
3 4	Door Jamb	0.1	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb		F L N/A	Y				
	Threshold	.	L N/A	Y				
	Closet Door	.	L N/A	Y				
A	Cl Door Edge	.	F L N/A	Y				
B	Cl Casing	.	L N/A	Y				
C	Closet Jamb	.	F L N/A	Y				
D	Closet Walls	.	L N/A	Y				
	Cl Baseboard	.	L N/A	Y				
1	Closet Pole	.	L N/A	Y				
2	Closet Shelf	.	L N/A	Y				
3	Cl Supports	.	L N/A	Y				
4	Closet Floor	.	L ☐ (dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN.)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	0.1	M/I A/M L N/A	Y				
B	Win Apron	/	L N/A	Y				
C	Win Casing	0.1	L N/A	Y				
D	Header Stop	0.1	M/I L N/A	Y				
	Int Stops	0.2	M/I L N/A	Y				
1	Win Int Sash	0.1	M/I L N/A	Y				
2	Exterior Sill	0.1	M/I SF L N/A	Y				
3	Part Bead	/	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	0.2	M/I L N/A	Y				
A	Window Sill	0.1	M/I A/M L N/A	Y				
B	Win Apron	/	L N/A	Y				
C	Win Casing	0.2	L N/A	Y				
D	Header Stop	0.1	M/I L N/A	Y				
	Int Stops	0.1	M/I L N/A	Y				
1	Win Int Sash	VR	M/I L N/A	Y				
2	Exterior Sill	VR	M/I SF L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A B	Fireplace	.	L N/A	Y				
C D	Mantle	.	L N/A	Y				
A B C D	Win Above 5'	.	L N/A	Y				
	Ceiling Molding	.	L N/A	Y				
B	Cornice	.	F M/I A/M L N/A	Y				
	Top	0.1	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

Inspector (print)	Lic #	Signature	Date
MEL BLACKMAN	M-1377		08- 27 - 2018

Risk Assessor (print)	Lic #	Signature	Date
MEL BLACKMAN	R-1377		/ /

Address of Property: 145 MAIN ST. Apt # DAY CARE City: GROTON

BATHROOM # 1

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	1 METH
A B C D	Up Walls	0.4	L N/A	Y				
A B C D	Low Walls	Tile	L N/A	Y				
A B C D	Baseboards	/	L N/A	Y				
A B C D	Chair Rail	/	L N/A	Y				
A B C D	Radiator	0.5	L N/A	Y				
	Floor	Tile	L ☐(dust) N/A	Y				
	Ceiling	0.2	L N/A	Y				
A B	Door	0.0	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	0.4	L N/A	Y				
3 4	Door Jamb	0.2	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door Stop	0.3	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A	Closet Door	.	L N/A	Y				
B	Cl Door Edge	.	F L N/A	Y				
C	Cl Casing	.	L N/A	Y				
D	Closet Jamb		F L N/A	Y				
	Closet Walls		L N/A	Y				
1	Cl Baseboard	.	L N/A	Y				
2	Closet Pole	.	L N/A	Y				
3	Closet Shelf	.	L N/A	Y				
4	Cl Supports	.	L N/A	Y				
	Closet Floor	.	L ☐(dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				
A	Window Box	0.5	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
			F M/I A/M L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B	Up Cab Frame	.	L N/A	Y				
C D	Up Cab Door	.	L N/A	Y				
	Up Cab Walls	.	L N/A	Y				
1 2	Up Cab Shlvs	.	L N/A	Y				
3 4	Supports	.	L N/A	Y				
	Low Cab Fram		L N/A	Y				
A B	Low Cab Door	.	L N/A	Y				
C D	Low Cab Walls	.	L N/A	Y				
	Low Cab Shlvs	.	L N/A	Y				
1 2	Supports	.	L N/A	Y				
3 4	Drawers	.	L N/A	Y				
A	Window Sill	0.0	M/I A/M L N/A	Y				
B	Win Apron	0.8	L N/A	Y				
C	Win Casing	0.3	L N/A	Y				
D	Header Stop	0.0	M/I L N/A	Y				
	Int Stops	0.2	M/I L N/A	Y				
1	Win Int Sash	W	M/I L N/A	Y				
2	Exterior Sill	W	M/I SF L N/A	Y				
3	Part Bead	W	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	W	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A B C D	Medicine Cab	.	L N/A	Y				
A B C D	Win Above 5'	.	L N/A	Y				
	Ceiling Molding	.	L N/A	Y				
	Bathtub	.	L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

MEL BLACKMAN	M-1377		08- 27 - 2018	
Inspector (print)	Lic #	Signature	Date	
MEL BLACKMAN	R-1377		/ /	
Risk Assessor (print)	Lic #	Signature	Date	

Page 21 of 40

Address of Property: 145 MAIN ST. Apt # DAY CARE City: GROTON

BATHROOM # 2

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	1 METH
A B C D	Up Walls	OB	L N/A	Y				
A B C D	Low Walls	Tile	L N/A	Y				
A B C D	Baseboards	.	L N/A	Y				
A B C D	Chair Rail	.	L N/A	Y				
A B C D	Radiator	.	L N/A	Y				
	Floor	Tile	L ☐ (dust) N/A	Y				
	Ceiling	OC	L N/A	Y				
A B	Door	OP	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	OY	L N/A	Y				
3 4	Door Jamb	OY	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B	Door (Stall)	OP	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A	Closet Door	.	L N/A	Y				
B	Cl Door Edge	.	F L N/A	Y				
C	Cl Casing	.	L N/A	Y				
D	Closet Jamb	.	F L N/A	Y				
	Closet Walls	.	L N/A	Y				
1	Cl Baseboard	.	L N/A	Y				
2	Closet Pole	.	L N/A	Y				
3	Closet Shelf	.	L N/A	Y				
4	Cl Supports	.	L N/A	Y				
	Closet Floor	.	L ☐ (dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN)

LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B	Up Cab Frame	.	L N/A	Y				
C D	Up Cab Door	.	L N/A	Y				
	Up Cab Walls	.	L N/A	Y				
1 2	Up Cab Shlvs	.	L N/A	Y				
3 4	Supports	.	L N/A	Y				
	Low Cab Frame	.	L N/A	Y				
A B	Low Cab Door	.	L N/A	Y				
C D	Low Cab Walls	.	L N/A	Y				
	Low Cab Shlvs	.	L N/A	Y				
1 2	Supports	.	L N/A	Y				
3 4	Drawers	.	L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A B C D	Medicine Cab	.	L N/A	Y				
A B C D	Win Above 5'	.	L N/A	Y				
	Ceiling Molding	.	L N/A	Y				
	Bathtub	.	L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

MEL BLACKMAN — M-1377 — Signature — 08- 27 - 2018

Inspector (print) — Lic # — Date

MEL BLACKMAN — R-1377 — / /

Risk Assessor (print) — Lic # — Signature — Date

Address of Property: 145 MAIN ST. Apt # DAY CARE City: GROTON

BATHROOM #3

Page 18 of 78 22 40

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	1 METH
A B C D	Up Walls	04	L N/A	Y				
A B C D	Low Walls	01	L N/A	Y				
A B C D	Baseboards	00	L N/A	Y				
A B C D	Chair Rail	03	L N/A	Y				
A B C D	Radiator	06	L N/A	Y				
	Floor	02	L ☐(dust) N/A	Y				
	Ceiling	0.4	L N/A	Y				
A B	Door	00	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	03	L N/A	Y				
3 4	Door Jamb	00	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge		F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A	Closet Door	.	L N/A	Y				
B	Cl Door Edge	.	F L N/A	Y				
C	Cl Casing	.	L N/A	Y				
D	Closet Jamb	.	F L N/A	Y				
	Closet Walls		L N/A	Y				
1	Cl Baseboard	.	L N/A	Y				
2	Closet Pole	.	L N/A	Y				
3	Closet Shelf	.	L N/A	Y				
4	Cl Supports	.	L N/A	Y				
	Closet Floor	.	L ☐(dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				
(2)	Shelves	02	F Mt A/M L N/A	Y				
		.	F Mt A/M L N/A	Y				
		.	F Mt A/M L N/A	Y				
			F Mt A/M L N/A	Y				
			F Mt A/M L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B	Up Cab Frame	.	L N/A	Y				
C D	Up Cab Door	.	L N/A	Y				
	Up Cab Walls	.	L N/A	Y				
1 2	Up Cab Shlvs	.	L N/A	Y				
3 4	Supports	.	L N/A	Y				
	Low Cab Fram	.	L N/A	Y				
A B	Low Cab Door	.	L N/A	Y				
C D	Low Cab Walls	.	L N/A	Y				
	Low Cab Shlvs	.	L N/A	Y				
1 2	Supports	.	L N/A	Y				
3 4	Drawers	.	L N/A	Y				
A	Window Sill	.	Mt A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	Mt L N/A	Y				
	Int Stops		Mt L N/A	Y				
1	Win Int Sash	.	Mt L N/A	Y				
2	Exterior Sill	.	Mt SF L N/A	Y				
3	Part Bead	.	Mt L N/A	Y				
4	Blind Stop	.	Mt SF L N/A	Y				
	Win Ext Sash	.	Mt L N/A	Y				
(2)	Window Sill	02	Mt A/M L N/A	Y				
B	Win Apron	04	L N/A	Y				
C	Win Casing	01	L N/A	Y				
D	Header Stop	03	Mt L N/A	Y				
	Int Stops	03	Mt L N/A	Y				
1	Win Int Sash	VR	Mt L N/A	Y				
2	Exterior Sill	VR	Mt SF L N/A	Y				
3	Part Bead	VR	Mt L N/A	Y				
4	Blind Stop	/	Mt SF L N/A	Y				
	Win Ext Sash	VR	Mt L N/A	Y				
A B C D	Medicine Cab		L N/A	Y				
A B C D	Win Above 5'	.	L N/A	Y				
	Ceiling Molding	.	L N/A	Y				
	Bathtub	.	L N/A	Y				
		.	F Mt A/M L N/A	Y				
		.	F Mt A/M L N/A	Y				
		.	F Mt A/M L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN)

LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

COMMENTS / STRUCTURAL DEFECTS:

☐ *Check the box if this ROOM is RULED OUT for encapsulation* because there are 3 or more A/M surfaces with adhesion problems

LI/RA Rep 2017 Bath

Joseph P Cataldo — Inspector (print)
3147 — Lic #
Signature
6 / 16 / 23 — Date

Risk Assessor (print) — Lic# — Signature — Date / /

Address of Property: 145 Main St — Apt. # None — City: Groton 01450

BATHROOM # 4

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.2	L N/A	Y				
A B C D	Low Walls	0.1	L N/A	Y				
A B C D	Baseboards	/	L N/A	Y				
A B C D	Chair Rail	/	L N/A	Y				
A B C D	Radiator	/	L N/A	Y				
	Floor	0.4	L ☐ (dust) N/A	Y				
	Ceiling	DC	L N/A	Y				
A B	Door	0.1	L N/A	Y				
C D	Door Edge	0.1	F L N/A	Y				
1 2	Door Casing	0.2	L N/A	Y				
3 4	Door Jamb	0.1	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
	Closet Door	.	L N/A	Y				
A	Cl Door Edge	.	F L N/A	Y				
B	Cl Casing	.	L N/A	Y				
C	Closet Jamb	.	F L N/A	Y				
D	Closet Walls	.	L N/A	Y				
	Cl Baseboard	.	L N/A	Y				
1	Closet Pole	.	L N/A	Y				
2	Closet Shelf	.	L N/A	Y				
3	Cl Supports	.	L N/A	Y				
4	Closet Floor	.	L ☐ (dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B	Up Cab Frame	.	L N/A	Y				
C D	Up Cab Door	.	L N/A	Y				
	Up Cab Walls	.	L N/A	Y				
1 2	Up Cab Shlvs	.	L N/A	Y				
3 4	Supports	.	L N/A	Y				
	Low Cab Fram	.	L N/A	Y				
A B	Low Cab Door	.	L N/A	Y				
C D	Low Cab Walls	.	L N/A	Y				
	Low Cab Shlvs	.	L N/A	Y				
1 2	Supports	.	L N/A	Y				
3 4	Drawers	.	L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A B C D	Win Above 5'	.	L N/A	Y				
	Ceiling Molding	.	L N/A	Y				
A B C D	Medicine Cab	.	L N/A	Y				
	Stalls	0.1	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN.)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

COMMENTS / STRUCTURAL DEFECTS:

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

Joseph P Cataldo | 3147 | J P Cataldo | 6 / 16 / 23
Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic# | Signature | Date / /

Address of Property: 145 Main St | Apt. # None | City: Groton 01450

BATHROOM # 5

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.2	L N/A	Y				
A B C D	Low Walls	0.1	L N/A	Y				
A B C D	Baseboards	/	L N/A	Y				
A B C D	Chair Rail	/	L N/A	Y				
A B C D	Radiator	/	L N/A	Y				
	Floor	0.3	L ☐ (dust) N/A	Y				
	Ceiling	DC	L N/A	Y				
A B	Door	0.1	L N/A	Y				
C D	Door Edge	0.1	F L N/A	Y				
1 2	Door Casing	0.1	L N/A	Y				
3 4	Door Jamb	0.2	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
	Closet Door	.	L N/A	Y				
A	Cl Door Edge	.	F L N/A	Y				
B	Cl Casing	.	L N/A	Y				
C	Closet Jamb	.	F L N/A	Y				
D	Closet Walls	.	L N/A	Y				
	Cl Baseboard	.	L N/A	Y				
1	Closet Pole	.	L N/A	Y				
2	Closet Shelf	.	L N/A	Y				
3	Cl Supports	.	L N/A	Y				
4	Closet Floor	.	L ☐ (dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B	Up Cab Frame	.	L N/A	Y				
C D	Up Cab Door	.	L N/A	Y				
	Up Cab Walls	.	L N/A	Y				
1 2	Up Cab Shlvs	.	L N/A	Y				
3 4	Supports	.	L N/A	Y				
	Low Cab Fram	.	L N/A	Y				
A B	Low Cab Door	.	L N/A	Y				
C D	Low Cab Walls	.	L N/A	Y				
	Low Cab Shlvs	.	L N/A	Y				
1 2	Supports	.	L N/A	Y				
3 4	Drawers	.	L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A B C D	Win Above 5'	.	L N/A	Y				
	Ceiling Molding	.	L N/A	Y				
A B C D	Medicine Cab	.	L N/A	Y				
A	Sill-116	0.1	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN.)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

COMMENTS / STRUCTURAL DEFECTS:

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

MEL BLACKMAN	M-1377		08- 27 - 2018
Inspector (print)	Lic #	Signature	Date
MEL BLACKMAN	R-1377		/ /
Risk Assessor (print)	Lic #	Signature	Date

Address of Property: 145 MAIN ST. Apt # DAYCARE City: GROTON

HALLWAY: Interior # 1 or Common Hallway: Front Rear Floor # ___

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	00	L N/A	Y				
A B C D	Low Walls	04	L N/A	Y				
A B C D	Baseboards	01	L N/A	Y				
A B C D	Chair Rail	02	L N/A	Y				
A B C D	Radiator	/	L N/A	Y				
	Floor	00	L ☐ (dust) N/A	Y				
	Ceiling	04	L N/A	Y				
A B	Door	00	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	02	L N/A	Y				
3 4	Door Jamb	03	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	/	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	00	L N/A	Y				
3 4	Door Jamb	01	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	00	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	04	L N/A	Y				
3 4	Door Jamb	03	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A	Closet Door	00	L N/A	Y				
B	Cl Door Edge	/	F L N/A	Y				
C	Cl Casing	03	L N/A	Y				
D	Closet Jamb	00	F L N/A	Y				
	Closet Walls	03	L N/A	Y				
1	Cl Baseboard	03	L N/A	Y				
2	Closet Pole	/	L N/A	Y				
3	Closet Shelf	00	L N/A	Y				
4	Cl Supports	02	L N/A	Y				
	Closet Floor	CN	L ☐ (dust) N/A	Y				
	Closet Ceiling	OC	L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Closet Door	.	L N/A	Y				
B	Cl Door Edge	.	F L N/A	Y				
C	Cl Casing	.	L N/A	Y				
D	Closet Jamb	.	F L N/A	Y				
	Closet Walls	.	L N/A	Y				
1	Cl Baseboard	.	L N/A	Y				
2	Closet Pole	.	L N/A	Y				
3	Closet Shelf	.	L N/A	Y				
4	Cl Supports	.	L N/A	Y				
	Closet Floor		L ☐ (dust) N/A	Y				
	Closet Ceiling		L N/A	Y				
A	Window Sill	.	MI A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	MI L N/A	Y				
	Int Stops	.	MI L N/A	Y				
1	Win Int Sash	.	MI L N/A	Y				
2	Exterior Sill	.	MI SF L N/A	Y				
3	Part Bead	.	MI L N/A	Y				
4	Blind Stop	.	MI SF L N/A	Y				
	Win Ext Sash	.	MI L N/A	Y				
A	Window Sill	.	MI A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	MI L N/A	Y				
	Int Stops	.	MI L N/A	Y				
1	Win Int Sash	.	MI L N/A	Y				
2	Exterior Sill	.	MI SF L N/A	Y				
3	Part Bead	.	MI L N/A	Y				
4	Blind Stop	.	MI SF L N/A	Y				
	Win Ext Sash	.	MI L N/A	Y				
A B C D	Win Above 5'	.	L N/A	Y				
	Ceiling Molding	.	L N/A	Y				
A B C D		.	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN)

ONE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

COMMENTS / STRUCTURAL DEFECTS:

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

MEL BLACKMAN — M-1377 — Signature — 08- 27 - 2018
Inspector (print) — Lic # — Date

MEL BLACKMAN — R-1377 — / /
Risk Assessor (print) — Lic # — Signature — Date

Address of Property: 145 MAIN ST. Apt # DAYCARE City: GROTON

HALLWAY: Interior #(2) or Common Hallway: Front Rear Floor # ___

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.0	L N/A	Y				
A B C D	Low Walls	4.1	L N/A	Y				
A B C D	Baseboards	0.2	L N/A	Y				
A B C D	Chair Rail	0.2	L N/A	Y				
A B C D	Radiator	/	L N/A	Y				
	Floor	0.0	L ☐ (dust) N/A	Y				
	Ceiling	0.2	L N/A	Y				
(A) B	Door	/	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
(1) 2	Door Casing	0.2	L N/A	Y				
3 4	Door Jamb	0.2	F L N/A	Y				
	Threshold	/	L N/A	Y				
(A) B	Door	0.1	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 (2)	Door Casing	0.3	L N/A	Y				
3 4	Door Jamb	0.1	F L N/A	Y				
	Threshold	/	L N/A	Y				
(A) B	Door	0.0	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	0.4	L N/A	Y				
(3) 4	Door Jamb	0.2	F L N/A	Y				
	Threshold	/	L N/A	Y				
(A) B	Door	0.2	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	0.1	L N/A	Y				
3 (4)	Door Jamb	0.0	F L N/A	Y				
	Threshold	/	L N/A	Y				
(A) (D)	Panel Frame	0.2	L N/A	Y				
(B)	Hose Door	0.3	F L N/A	Y				
(C)	Deadlights	0.5	L N/A	Y				
D		.	F L N/A	Y				
	Closet Walls	.	L N/A	Y				
1	Cl Baseboard	.	L N/A	Y				
2	Closet Pole	.	L N/A	Y				
3	Closet Shelf	.	L N/A	Y				
4	Cl Supports	.	L N/A	Y				
	Closet Floor	.	L ☐ (dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Closet Door	.	L N/A	Y				
B	Cl Door Edge	.	F L N/A	Y				
C	Cl Casing	.	L N/A	Y				
D	Closet Jamb	.	F L N/A	Y				
	Closet Walls	.	L N/A	Y				
1	Cl Baseboard	.	L N/A	Y				
2	Closet Pole	.	L N/A	Y				
3	Closet Shelf	.	L N/A	Y				
4	Cl Supports	.	L N/A	Y				
	Closet Floor	.	L ☐ (dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A	Window Sill	0.0	M/I A/M L N/A	Y				
(B)	Win Apron	0.0	L N/A	Y				
C	Win Casing	0.2	L N/A	Y				
D	Header Stop	0.1	M/I L N/A	Y				
	Int Stops	0.0	M/I L N/A	Y				
1	Win Int Sash	NC	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead		M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
	Win Above 5'	N/A	L N/A	Y				
	Ceiling Molding	/	L N/A	Y				
A B	Sidelights	0.4	L N/A	Y				
(A) B	Door	0.2	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	0.3	L N/A	Y				
3 4	Door Jamb	0.0	F L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN)

LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

COMMENTS / STRUCTURAL DEFECTS:

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

MEL BLACKMAN	M-1377		08- 27 - 2018	Page 21 Of 28
Inspector (print)	Lic #	Signature	Date	22 40
MEL BLACKMAN	R-1377		/ /	
Risk Assessor (print)	Lic #	Signature	Date	
Address of Property: 145 MAIN ST.		Apt # DAYCARE	City: GROTON	

HALL WAY: EXTRA DOORS (2) CONTINUED

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	.	L N/A	Y				
A B C D	Low Walls	.	L N/A	Y				
A B C D	Baseboards	.	L N/A	Y				
A B C D	Chair Rail	.	L N/A	Y				
A B C D	Radiator		L N/A	Y				
	Floor	.	L ☐ (dust) N/A	Y				
	Ceiling	.	L N/A	Y				
A B C D #1	Door	02	L N/A	Y				
	Door Edge	✓	F L N/A	Y				
	Door Casing	01	L N/A	Y				
	Door Jamb	02	F L N/A	Y				
	Threshold	✓	L N/A	Y				
A B C D #2	Door	01	L N/A	Y				
	Door Edge	✓	F L N/A	Y				
	Door Casing	04	L N/A	Y				
	Door Jamb	03	F L N/A	Y				
	Threshold	✓	L N/A	Y				
A B C D #	Door	03	L N/A	Y				
	Door Edge	✓	F L N/A	Y				
	Door Casing	04	L N/A	Y				
	Door Jamb	04	F L N/A	Y				
	Threshold	✓	L N/A	Y				
A B C D #1	Door	00	L N/A	Y				
	Door Edge	✓	F L N/A	Y				
	Door Casing	03	L N/A	Y				
	Door Jamb	00	F L N/A	Y				
	Threshold	✓	L N/A	Y				
A B C D #2	Door	03	L N/A	Y				
	Door Edge	✓	F L N/A	Y				
	Door Casing	00	L N/A	Y				
	Door Jamb	01	F L N/A	Y				
	Threshold	✓	L N/A	Y				
A B C D #3	Door	02	L N/A	Y				
	Door Edge	✓	F L N/A	Y				
	Door Casing	02	L N/A	Y				
	Door Jamb	03	F L N/A	Y				
	Threshold	✓	L N/A	Y				
		.	F M/I A/M L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN)

LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D #	Door	.	L N/A	Y				
	Door Edge	.	F L N/A	Y				
	Door Casing	.	L N/A	Y				
	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B C D #	Door	.	L N/A	Y				
	Door Edge	.	F L N/A	Y				
	Door Casing	.	L N/A	Y				
	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B C D #	Door	.	L N/A	Y				
	Door Edge	.	F L N/A	Y				
	Door Casing	.	L N/A	Y				
	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B C D #	Door	.	L N/A	Y				
	Door Edge	.	F L N/A	Y				
	Door Casing	.	L N/A	Y				
	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B C D #	Door	.	L N/A	Y				
	Door Edge	.	F L N/A	Y				
	Door Casing	.	L N/A	Y				
	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B C D #	Door	.	L N/A	Y				
	Door Edge	.	F L N/A	Y				
	Door Casing	.	L N/A	Y				
	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B C D #	Door	.	L N/A	Y				
	Door Edge	.	F L N/A	Y				
	Door Casing	.	L N/A	Y				
	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B C D	Door	.	L N/A	Y				
	Door Edge	.	F L N/A	Y				
	Door Casing	.	L N/A	Y				
	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B C D	Win.Above 5'	.	L N/A	Y				
	Ceiling Molding	.	L N/A	Y				
		.	F M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

MEL BLACKMAN — Inspector (print) — Lic # M-1377 — Signature — Date 08- 27 - 2018

MEL BLACKMAN — Risk Assessor (print) — Lic # R-1377 — Signature — Date / /

Address of Property: 145 MAIN ST. Apt # DAYCARE City: GROTON

HALLWAY: Interior # 3 or Common Hallway: Front Rear Floor #

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	03	L N/A	Y				
A B C D	Low Walls	03	L N/A	Y				
A B C D	Baseboards	00	L N/A	Y				
A B C D	Chair Rail	02	L N/A	Y				
A B C D	Radiator Cover	01	L N/A	Y				
	Floor	00	L ☐ (dust) N/A	Y				
	Ceiling	03	L N/A	Y				
A B C D 1 2 3 4	Door	03	L N/A	Y				
	Door Edge	/	F L N/A	Y				
	Door Casing	01	L N/A	Y				
	Door Jamb	03	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B C D 1 2 3 4	Door	0.1	L N/A	Y				
	Door Edge	/	F L N/A	Y				
	Door Casing	03	L N/A	Y				
	Door Jamb	00	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B C D 1 2 3 4	Door	03	L N/A	Y				
	Door Edge	/	F L N/A	Y				
	Door Casing	00	L N/A	Y				
	Door Jamb	01	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B C D 1 2 3 4	Door	01	L N/A	Y				
	Door Edge	/	F L N/A	Y				
	Door Casing	02	L N/A	Y				
	Door Jamb	00	F L N/A	Y				
	Threshold	/	L N/A	Y				
A	Closet Door	/	L N/A	Y				
B	Cl Door Edge	/	F L N/A	Y				
C	Cl Casing	/	L N/A	Y				
D	Closet Jamb	/	F L N/A	Y				
Cover	Closet Walls Cover	02	L N/A	Y				
1	Cl Baseboard	/	L N/A	Y				
2	Closet Pole	/	L N/A	Y				
3	Closet Shelf	/	L N/A	Y				
4	Cl Supports	/	L N/A	Y				
	Closet Floor	/	L ☐ (dust) N/A	Y				
	Closet Ceiling	/	L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Closet Door	02	L N/A	Y				
B	Cl Door Edge	/	F L N/A	Y				
C	Cl Casing Cover	00	L N/A	Y				
D	Closet Jamb	00	F L N/A	Y				
	Closet Walls	/	L N/A	Y				
1	Cl Baseboard	/	L N/A	Y				
2	Closet Pole	/	L N/A	Y				
3	Closet Shelf	/	L N/A	Y				
4	Cl Supports	/	L N/A	Y				
	Closet Floor	/	L ☐ (dust) N/A	Y				
	Closet Ceiling	/	L N/A	Y				
A	Window Sill	/	M/I A/M L N/A	Y				
B	Win Apron	/	L N/A	Y				
C	Win Casing	/	L N/A	Y				
D	Header Stop	/	M/I L N/A	Y				
	Int Stops	/	M/I L N/A	Y				
1	Win Int Sash	/	M/I L N/A	Y				
2	Exterior Sill	/	M/I SF L N/A	Y				
3	Part Bead	/	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	/	M/I L N/A	Y				
A	Window Sill	/	M/I A/M L N/A	Y				
B	Win Apron	/	L N/A	Y				
C	Win Casing	/	L N/A	Y				
D	Header Stop	/	M/I L N/A	Y				
	Int Stops	/	M/I L N/A	Y				
1	Win Int Sash	/	M/I L N/A	Y				
2	Exterior Sill	/	M/I SF L N/A	Y				
3	Part Bead	/	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	/	M/I L N/A	Y				
A B C D	Win Above 5'	/	L N/A	Y				
	Ceiling Molding	/	L N/A	Y				
A B C D	Sidelights	04	L N/A	Y				
A B C D 1 2 3 4	Door	01	L N/A	Y				
	Door Edge	/	F L N/A	Y				
	Door Casing	04	L N/A	Y				
	Door Jamb	01	F L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN)

LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

COMMENTS / STRUCTURAL DEFECTS:

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

Joseph P Cataldo | 3147 | Signature | 6 / 16 / 23 | Page 29 of 40
Inspector (print) | Lic # | Date

Risk Assessor (print) | Lic # | Signature | / / Date

Address of Property: 145 Main St | Apt. # None | City: Groton 01450

HALLWAY: Interior # (4) or Common Hallway: (Front) Rear Floor # Bsmt Bottom of Front stairs

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
(A B C D)	Up Walls	0.2	L N/A	Y				
(A B C D)	Low Walls	0.1	L N/A	Y				
(A B C D)	Baseboards	0.2	L N/A	Y				
(A B C D)	Chair Rail	0.0	L N/A	Y				
A B C D	Radiator	/	L N/A	Y				
	Floor	0.2	L ☐ (dust) N/A	Y				
	Ceiling	0.1	L N/A	Y				
(A) B C D 1 2 3 4	Door	0.1	L N/A	Y				
	Door Edge	0.1	F L N/A	Y				
	Door Casing	0.1	L N/A	Y				
	Door Jamb	0.0	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B (C) D 1 2 3 4	Door	0.0	L N/A	Y				
	Door Edge	0.2	F L N/A	Y				
	Door Casing	0.1	L N/A	Y				
	Door Jamb	0.1	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B C D 1 2 3 4	Door	.	L N/A	Y				
	Door Edge	.	F L N/A	Y				
	Door Casing	.	L N/A	Y				
	Door Jamb		F L N/A	Y				
	Threshold	.	L N/A	Y				
A B C D 1 2 3 4	Door	.	L N/A	Y				
	Door Edge	.	F L N/A	Y				
	Door Casing	.	L N/A	Y				
	Door Jamb	.	F L N/A	Y				
A B C D 1 2 3 4	Closet Door	.	L N/A	Y				
	Cl Door Edge		F L N/A	Y				
	Cl Casing	.	L N/A	Y				
	Closet Jamb	.	F L N/A	Y				
	Closet Walls	.	L N/A	Y				
	Cl Baseboard	.	L N/A	Y				
	Closet Pole	.	L N/A	Y				
	Closet Shelf		L N/A	Y				
	Cl Supports		L N/A	Y				
	Closet Floor		L ☐ (dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D 1 2 3 4	Closet Door	.	L N/A	Y				
	Cl Door Edge	.	F L N/A	Y				
	Cl Casing	.	L N/A	Y				
	Closet Jamb	.	F L N/A	Y				
	Closet Walls	.	L N/A	Y				
	Cl Baseboard	.	L N/A	Y				
	Closet Pole	.	L N/A	Y				
	Closet Shelf	.	L N/A	Y				
	Cl Supports	.	L N/A	Y				
	Closet Floor	.	L ☐ (dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				
A B C D 1 2 3 4	Window Sill	.	M/I A/M L N/A	Y				
	Win Apron	.	L N/A	Y				
	Win Casing		L N/A	Y				
	Header Stop		M/I L N/A	Y				
	Int Stops		M/I L N/A	Y				
	Win Int Sash	.	M/I L N/A	Y				
	Exterior Sill	.	M/I SF L N/A	Y				
	Part Bead	.	M/I L N/A	Y				
	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash		M/I L N/A	Y				
A B C D 1 2 3 4	Window Sill	.	M/I A/M L N/A	Y				
	Win Apron	.	L N/A	Y				
	Win Casing	.	L N/A	Y				
	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
	Win Int Sash	.	M/I L N/A	Y				
	Exterior Sill	.	M/I SF L N/A	Y				
	Part Bead	.	M/I L N/A	Y				
	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A B C D	Win Above 5'	.	L N/A	Y				
	Ceiling Molding	.	L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN.)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

Joseph P Cataldo | 3147 | J P Cataldo | 6 / 16 / 23
Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic # | Signature | / / Date

Address of Property: 145 Main St | Apt. # None | City: Groton 01450

HALLWAY: Interior # 3 or Common Hallway: Front Rear Floor # 1 of 2

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.2	L N/A	Y				
A B C D	Low Walls	0.1	L N/A	Y				
A B C D	Baseboards	0.1	L N/A	Y				
A B C D	Chair Rail	0.1	L N/A	Y				
A B C D	Radiator	/	L N/A	Y				
	Floor	0.1	L ☐ (dust) N/A	Y				
	Ceiling	2.4	L N/A	Y				
A B	Door	0.1	L N/A	Y				
C D	Door Edge	0.1	F L N/A	Y				
1 2	Door Casing	0.2	L N/A	Y				
3 4	Door Jamb	0.1	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	0.1	L N/A	Y				
C D	Door Edge	0.2	F L N/A	Y				
1 2	Door Casing	0.1	L N/A	Y				
3 4	Door Jamb	0.1	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	0.2	L N/A	Y				
C D	Door Edge	0.1	F L N/A	Y				
1 2	Door Casing	0.1	L N/A	Y				
3 4	Door Jamb	0.2	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	0.0	L N/A	Y				
C D	Door Edge	0.1	F L N/A	Y				
1 2	Door Casing	0.2	L N/A	Y				
3 4	Door Jamb	0.1	F L N/A	Y				
	Closet Door	.	L N/A	Y				
A	Cl Door Edge	.	F L N/A	Y				
B	Cl Casing	.	L N/A	Y				
C	Closet Jamb	.	F L N/A	Y				
D	Closet Walls	.	L N/A	Y				
	Cl Baseboard	.	L N/A	Y				
1	Closet Pole	.	L N/A	Y				
2	Closet Shelf	.	L N/A	Y				
3	Cl Supports	.	L N/A	Y				
4	Closet Floor	.	L ☐ (dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
	Closet Door	/	L N/A	Y				
A	Cl Door Edge	.	F L N/A	Y				
B	Cl Casing	.	L N/A	Y				
C	Closet Jamb	.	F L N/A	Y				
D	Closet Walls	.	L N/A	Y				
	Cl Baseboard	.	L N/A	Y				
1	Closet Pole	.	L N/A	Y				
2	Closet Shelf	.	L N/A	Y				
3	Cl Supports	.	L N/A	Y				
4	Closet Floor	.	L ☐ (dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				
A	Window Sill	0.1	M/I A/M L N/A	Y	Blocked off opening			
B	Win Apron	/	L N/A	Y				
C	Win Casing	0.2	L N/A	Y				
D	Header Stop	0.2	M/I L N/A	Y				
	Int Stops	0.1	M/I L N/A	Y				
1	Win Int Sash	/	M/I L N/A	Y				
2	Exterior Sill	/	M/I SF L N/A	Y				
3	Part Bead	/	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	/	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A B C D	Win Above 5'	.	L N/A	Y				
	Ceiling Molding	.	L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN.)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

Joseph P Cataldo — 3147 — 6 / 16 / 23

Inspector (print) — Lic # — Signature — Date

Page 31 of 40

Risk Assessor (print) — Lic # — Signature — Date / /

Address of Property: 145 Main St — Apt. # None — City: Groton 01450

CONTINUATION OF ROOM (Hallway #5) 2 of 2

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B	Door	0.1	L N/A	Y				
C D	Door Edge	0.2	F L N/A	Y				
	Door Casing	00	L N/A	Y				
	Door Jamb	0.1	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	0.1	L N/A	Y				
C D	Door Edge	N/A	F L N/A	Y				
1 2	Door Casing	0.1	L N/A	Y				
3 4	Door Jamb	N/A	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	0.1	L N/A	Y				
C D	Door Edge	N/A	F L N/A	Y				
1 2	Door Casing	0.1	L N/A	Y				
3 4	Door Jamb	0.1	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	0.2	L N/A	Y				
C D	Door Edge	N/A	F L N/A	Y				
1 2	Door Casing	0.1	L N/A	Y				
3 4	Door Jamb	N/A	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	0.1	L N/A	Y				
C D	Door Edge	N/A	F L N/A	Y				
1 2	Door Casing	0.2	L N/A	Y				
3 4	Door Jamb	N/A	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	0.1	L N/A	Y				
C D	Door Edge	N/A	F L N/A	Y				
	Door Casing	0.1	L N/A	Y				
	Door Jamb	N/A	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	/	L N/A	Y	Side Lites			
C D	Door Edge	/	F L N/A	Y	0.4			
1 2	Door Casing	0.1	L N/A	Y				
3 4	Door Jamb	0.2	F L N/A	Y				
	Threshold	/	L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN.)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B	Door	0.1	L N/A	Y				
C D	Door Edge	N/A	F L N/A	Y				
1 2	Door Casing	0.1	L N/A	Y				
3 4	Door Jamb	N/A	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	0.3	L N/A	Y				
C D	Door Edge	N/A	F L N/A	Y				
1 2	Door Casing	0.2	L N/A	Y				
3 4	Door Jamb	N/A	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	0.3	L N/A	Y				
C D	Door Edge	N/A	F L N/A	Y				
1 2	Door Casing	0.2	L N/A	Y				
3 4	Door Jamb	N/A	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	0.3	L N/A	Y				
C D	Door Edge	N/A	F L N/A	Y				
1 2	Door Casing	0.2	L N/A	Y				
3 4	Door Jamb	N/A	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge		F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb		F L N/A	Y				
	Threshold	.	L N/A	Y				
			F M/I A/M L N/A					
			F M/I A/M L N/A					
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

Joseph P Cataldo — 3147 — 6 / 16 / 23
Inspector (print) — Lic # — Signature — Date

Risk Assessor (print) — Lic # — Signature — Date / /

Address of Property: 145 Main St — Apt. # None — City: Groton 01450

HALLWAY: Interior # 6 or Common Hallway: Front Rear Floor #____

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.1	L N/A	Y				
A B C D	Low Walls	/	L N/A	Y				
A B C D	Baseboards	0.2	L N/A	Y				
A B C D	Chair Rail	/	L N/A	Y				
A B C D	Radiator	/	L N/A	Y				
	Floor	0.2	L ☐ (dust) N/A	Y				
	Ceiling	1.2	L N/A	Y				
A B	Door	/	L N/A	Y	Side Lites			
C D	Door Edge	/	F L N/A	Y	0.4			
1 2	Door Casing	0.1	L N/A	Y				
3 4	Door Jamb	0.1	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	0.1	L N/A	Y				
C D	Door Edge	0.1	F L N/A	Y				
1 2	Door Casing	0.2	L N/A	Y				
3 4	Door Jamb	0.2	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door (2)	0.1	L N/A	Y	Side Lites			
C D	Door Edge	0.2	F L N/A	Y	0.4			
1 2	Door Casing	0.1	L N/A	Y				
3 4	Door Jamb	0.1	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	0.1	L N/A	Y				
C D	Door Edge	0.2	F L N/A	Y				
1 2	Door Casing	0.1	L N/A	Y				
3 4	Door Jamb	0.1	F L N/A	Y				
	Closet Door	0.1	L N/A	Y	Storage			
A	Cl Door Edge	0.1	F L N/A	Y	Bin			
B	Cl Casing	/	L N/A	Y				
C	Closet Jamb	0.1	F L N/A	Y				
D	Closet Walls	/	L N/A	Y				
	Cl Baseboard	/	L N/A	Y				
1	Closet Pole	/	L N/A	Y				
2	Closet Shelf	/	L N/A	Y				
3	Cl Supports	/	L N/A	Y				
4	Closet Floor	/	L ☐ (dust) N/A	Y				
	Closet Ceiling	/	L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
	Closet Door	.	L N/A	Y				
A	Cl Door Edge	.	F L N/A	Y				
B	Cl Casing	.	L N/A	Y				
C	Closet Jamb	.	F L N/A	Y				
D	Closet Walls	.	L N/A	Y				
	Cl Baseboard	.	L N/A	Y				
1	Closet Pole	.	L N/A	Y				
2	Closet Shelf	.	L N/A	Y				
3	Cl Supports	.	L N/A	Y				
4	Closet Floor	.	L ☐ (dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A B C D	Win Above 5'	.	L N/A	Y				
	Ceiling Molding	.	L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (*MORE THAN 288 SQ. IN.*)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

MEL BLACKMAN — M-1377 — 08- 27 - 2018

Inspector (print) — Lic # — Signature — Date

MEL BLACKMAN — R-1377 — / /

Risk Assessor (print) — Lic # — Signature — Date

Address of Property: 145 MAIN ST. Apt # DAYCARE City: GROTON

STAIRCASE # (A) 1st to 2nd NOT to BASEMENT

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	06	L N/A	Y				
A B C D	Low Walls	52	L N/A	Y				
A B C D	Baseboards	03	L N/A	Y				
A B C D	Chair Rail	03	L N/A	Y				
A B C D	Radiator Cover	02	L N/A	Y				
	Floor	00	L ☐ (dust) N/A	Y				
	Ceiling	04	L N/A	Y				
A B	Door 1st fl	56	Q N/A	Y				
C D	Door Edge	19	G Q N/A	Y				
1 2	Door Casing	05	L N/A	Y				
3 4	Door Jamb	8.2	G Q N/A	Y				
	Threshold	00	L N/A	Y				
A B	Door 1st fl	01	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	00	L N/A	Y				
3 4	Door Jamb	02	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door 2nd fl	01	L N/A	Y				
C D	Door Edge	/	F L N/A	Y				
1 2	Door Casing	01	L N/A	Y				
3 4	Door Jamb	00	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb		F L N/A	Y				
	Threshold	.	L N/A	Y				
A	Closet Door	.	L N/A	Y				
B	Cl Door Edge	.	F L N/A	Y				
C	Cl Casing	.	L N/A	Y				
D	Closet Jamb	.	F L N/A	Y				
	Closet Walls	.	L N/A	Y				
1	Cl Baseboard	.	L N/A	Y				
2	Closet Pole	.	L N/A	Y				
3	Closet Shelf	.	L N/A	Y				
4	Cl Supports	.	L N/A	Y				
	Closet Floor	.	L ☐ (dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	04	M/I A/M L N/A	Y				
B	Win Apron	03	L N/A	Y				
C	Win Casing	03	L N/A	Y				
D	Header Stop	00	M/I L N/A	Y				
	Int Stops	02	M/I L N/A	Y				
1	Win Int Sash	01	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops		M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
	Newel Post	04	L N/A	Y				
	Railing Cap	05	A/M L N/A	Y				
	Handrail	04	A/M L N/A	Y				
	Balusters	/	L N/A	Y				
	Lower rail	03	L N/A	Y				
	Treads	05	F L N/A	Y				
	Risers	02	L N/A	Y				
	Stringer	04	L N/A	Y				
	Tread edge >5	/	L N/A	Y				
	Landing floor	03	L ☐ (dust) N/A	Y				
	Floor Edge	.	L N/A	Y				
	Floor Casing	.	L N/A	Y				
A B C D	Win Above 5'	.	L N/A	Y				
	Ceiling Molding	.	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge		F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

MEL BLACKMAN — Inspector (print) — M-1377 Lic # — Signature — 08- 27 - 2018 Date

MEL BLACKMAN — Risk Assessor (print) — R-1377 Lic # — Signature — / / Date

Address of Property: 145 MAIN ST. Apt # DAYCARE City: GROTON

STAIRCASE # (D) 1ST to 2nd - NOT to BASEMENT

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.3	L N/A	Y				
A B C D	Low Walls	4.4	(D) N/A	Y				
A B C D	Baseboards	02	L N/A	Y				
A B C D	Chair Rail	0.3	L N/A	Y				
A B C D	Radiator Cover	01	L N/A	Y				
	Floor	02	L ☐ (dust) N/A	Y				
	Ceiling	02	L N/A	Y				
A (B) C D 1 2 3 4	Door 1st fl	01	L N/A	Y				
	Door Edge	/	F L N/A	Y				
	Door Casing	03	L N/A	Y				
	Door Jamb	03	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B (C) D 1 2 3 4	Door 1st fl	08	L N/A	Y				
	Door Edge	/	F L N/A	Y				
	Door Casing	02	L N/A	Y				
	Door Jamb	02	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B C D 1 2 3 4	Door 1st fl	41	(D) N/A	Y				
	Door Edge	41	(F) (D) N/A	Y				
	Door Casing	0.0	L N/A	Y				
	Door Jamb	36	(F) (D) N/A	Y				
	Threshold	CW	L N/A	Y				
A (B) C D 1 2 3 4	Door 2nd fl	01	L N/A	Y				
	Door Edge	/	F L N/A	Y				
	Door Casing	00	L N/A	Y				
	Door Jamb	02	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B C D 1 2 3 4	Closet Door	/	L N/A	Y				
	Cl Door Edge	/	F L N/A	Y				
	Cl Casing	/	L N/A	Y				
	Closet Jamb	/	F L N/A	Y				
	Closet Walls	/	L N/A	Y				
	Cl Baseboard	/	L N/A	Y				
	Closet Pole	/	L N/A	Y				
	Closet Shelf	/	L N/A	Y				
	Cl Supports	/	L N/A	Y				
	Closet Floor	/	L ☐ (dust) N/A	Y				
	Closet Ceiling	/	L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D 1 2 3 4	Window Sill	/	M/I A/M L N/A	Y				
	Win Apron	/	L N/A	Y				
	Win Casing	/	L N/A	Y				
	Header Stop	/	M/I L N/A	Y				
	Int Stops	/	M/I L N/A	Y				
	Win Int Sash	/	M/I L N/A	Y				
	Exterior Sill	/	M/I SF L N/A	Y				
	Part Bead	/	M/I L N/A	Y				
	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	/	M/I L N/A	Y				
A B C D 1 2 3 4	Window Sill	/	M/I A/M L N/A	Y				
	Win Apron	/	L N/A	Y				
	Win Casing	/	L N/A	Y				
	Header Stop	/	M/I L N/A	Y				
	Int Stops	/	M/I L N/A	Y				
	Win Int Sash	/	M/I L N/A	Y				
	Exterior Sill	/	M/I SF L N/A	Y				
	Part Bead	/	M/I L N/A	Y				
	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	/	M/I L N/A	Y				
	Newel Post	03	L N/A	Y				
	Railing Cap	03	A/M L N/A	Y				
	Handrail	04	A/M L N/A	Y				
	Balusters	/	L N/A	Y				
	Lower rail	/	L N/A	Y				
	Treads	05	F L N/A	Y				
	Risers	04	L N/A	Y				
	Stringer	03	L N/A	Y				
	Tread edge >5	/	L N/A	Y				
	Landing floor	00	L ☐ (dust) N/A	Y				
	Floor Edge	/	L N/A	Y				
	Floor Casing	/	L N/A	Y				
A B C D	Win Above 5'	NA	L N/A	Y				
	Ceiling Molding	/	L N/A	Y				
A B C D 1 2 3 4	Door	/	L N/A	Y				
	Door Edge	/	F L N/A	Y				
	Door Casing	/	L N/A	Y				
	Door Jamb	/	F L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

Joseph P Cataldo | 3147 | [signature] | 6 / 16 / 23 | Page 35 Of 40

Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic # | Signature | / / Date

Address of Property: 145 Main St | Apt. # None | City: Groton 01450

STAIRCASE # Front 1st Fl. To Basement level

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	1.2	L N/A	Y				
A B C D	Low Walls	2.4	L N/A	Y				
A B C D	Baseboards	0.5	L N/A	Y				
A B C D	Chair Rail	0.1	L N/A	Y				
A B C D	Radiator	/	L N/A	Y				
	Floor	0.1	L ☐ (dust) N/A	Y				
	Ceiling	0.1	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold		L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold		L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Closet Door	.	L N/A	Y				
A	Cl Door Edge	.	F L N/A	Y				
B	Cl Casing	.	L N/A	Y				
C	Closet Jamb	.	F L N/A	Y				
D	Closet Walls	.	L N/A	Y				
	Cl Baseboard	.	L N/A	Y				
1	Closet Pole		L N/A	Y				
2	Closet Shelf		L N/A	Y				
3	Cl Supports		L N/A	Y				
4	Closet Floor		L ☐ (dust) N/A	Y				
	Closet Ceiling		L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron		L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing		L N/A	Y				
D	Header Stop		M/I L N/A	Y				
	Int Stops		M/I L N/A	Y				
1	Win Int Sash		M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
	Newel Post	0.1	L N/A	Y				
	Railing Cap	0.1	A/M L N/A	Y				
	Handrail	0.0	A/M L N/A	Y				
	Balusters	/	L N/A	Y				
	Lower rail	/	L N/A	Y				
	Treads	0.2	F L N/A	Y				
	Risers	0.1	L N/A	Y				
	Stringer	/	L N/A	Y				
	Tread edge >5"	/	L N/A	Y				
	Landing floor	0.1	L ☐ (dust) N/A	Y				
	Floor Edge	0.1	L N/A	Y				
	Floor Casing	/	L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN.)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

COMMENTS / STRUCTURAL DEFECTS:

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

Joseph P Cataldo | 3147 | [signature] | 6 / 16 / 23 | Page 36 of 40

Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic # | Signature | / / Date

Address of Property: 145 Main St | Apt. # None | City: Groton 01450

STAIRCASE # REAR Right 1st Fl. To Basement

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	1.3	L N/A	Y				
A B C D	Low Walls	2.9	L N/A	Y				
A B C D	Baseboards	0.2	L N/A	Y				
A B C D	Chair Rail	0.1	L N/A	Y				
A B C D	Radiator	/	L N/A	Y				
	Floor	0.0	L ☐ (dust) N/A	Y				
	Ceiling	0.4	L N/A	Y				
A B	Door	0.1	L N/A	Y	Bottom			
C D	Door Edge	0.1	F L N/A	Y	04			
1 2	Door Casing	0.2	L N/A	Y	Stairs			
3 4	Door Jamb	0.1	F L N/A	Y				
	Threshold	/	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing		L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing		L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
A B	Door	.	L N/A	Y				
C D	Door Edge	.	F L N/A	Y				
1 2	Door Casing		L N/A	Y				
3 4	Door Jamb		F L N/A	Y				
	Closet Door	.	L N/A	Y				
A	Cl Door Edge	.	F L N/A	Y				
B	Cl Casing	.	L N/A	Y				
C	Closet Jamb	.	F L N/A	Y				
D	Closet Walls		L N/A	Y				
	Cl Baseboard	.	L N/A	Y				
1	Closet Pole	.	L N/A	Y				
2	Closet Shelf	.	L N/A	Y				
3	Cl Supports	.	L N/A	Y				
4	Closet Floor	.	L ☐ (dust) N/A	Y				
	Closet Ceiling	.	L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron		L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	L N/A	Y				
C	Win Casing	.	L N/A	Y				
D	Header Stop	.	M/I L N/A	Y				
	Int Stops	.	M/I L N/A	Y				
1	Win Int Sash	.	M/I L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
	Newel Post	0.1	L N/A	Y				
	Railing Cap	0.0	A/M L N/A	Y				
	Handrail	0.0	A/M L N/A	Y				
	Balusters	.	L N/A	Y				
	Lower rail	.	L N/A	Y				
	Treads	0.1	F L N/A	Y				
	Risers	0.1	L N/A	Y				
	Stringer	.	L N/A	Y				
	Tread edge >5	0.2	L N/A	Y				
	Landing floor	0.0	L ☐ (dust) N/A	Y				
	Floor Edge	0.1	L N/A	Y				
	Floor Casing	.	L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				
		.	F M/I A/M L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can only be made intact by a Deleader (MORE THAN 288 SQ. IN.)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD

COMMENTS / STRUCTURAL DEFECTS:

☐ Check the box if this ROOM is RULED OUT for encapsulation because there are 3 or more A/M surfaces with adhesion problems

MEL BLACKMAN	M-1377	[signature]	08- 27 - 2018	Page ~~25~~ 37 Of ~~38~~ 40
Inspector (print)	Lic #	Signature	Date	
MEL BLACKMAN	R-1377		/ /	
Risk Assessor (print)	Lic #	Signature	Date	

Address of Property: 145 MAIN ST. Apt # DAYCARE City: GROTON

EXTERIOR A Side

SIDE A	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Siding	NC	L N/A	Y				
	Corner Boards	/	L N/A	Y				
	Lower Trim	/	L N/A	Y				
	Upper Trim	NA	0 N/A	Y				
	Win Above 5'	NA	L N/A	Y				
	Porch Above 5'	/	L N/A	Y				
A 1 2 3 4	Storm Door	/	L N/A	Y				
	Strm Door Edge	/	F L N/A	Y				
	Door	1.4	0 N/A	Y				
	Door Edge	1.6	F 0 N/A	Y				
	Door Casing	2.7	0 N/A	Y				
	Door Jamb	2.5	0 0 N/A	Y				
	Threshold	NC	L N/A	Y				
	Kickplate	/	L N/A	Y				
A 1 2 3 4	Storm Door	/	L N/A	Y				
	Strm Door Edge	/	F L N/A	Y				
	Door	/	L N/A	Y				
	Door Edge	/	F L N/A	Y				
	Door Casing	/	L N/A	Y				
	Door Jamb	/	F L N/A	Y				
	Threshold	/	L N/A	Y				
	Kickplate	/	L N/A	Y				
A 1 2 3 4	Door	/	L N/A	Y				
	Door Edge	/	F L N/A	Y				
	Door Casing	/	L N/A	Y				
	Door Jamb	/	F L N/A	Y				
	Threshold	/	L N/A	Y				
	Kickplate	/	L N/A	Y				
A #	Window Sill	/	A/M L N/A	Y				
	Win Casing	/	L N/A	Y				
	Window Sash	/	L N/A	Y				
A #	Window Sill	/	A/M L N/A	Y				
	Win Casing	/	L N/A	Y				
	Window Sash	/	L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in this box can only be made intact by a Deleader (MORE THAN 2880 SQ. IN.)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD
A				
A				
A				

SIDE A	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A #	Window Sill	/	A/M L N/A	Y				
	Win Casing	/	L N/A	Y				
	Window Sash	/	L N/A	Y				
A # YD	Cellar Win Sill	CN	A/M L N/A	Y				
	Cel Win Sash	NC	L N/A	Y				
	Cel Win Frame	CN	L N/A	Y				
	Screen Frame	/	L N/A	Y				
A #	Cellar Win Sill	/	A/M L N/A	Y				
	Cel Win Sash	/	L N/A	Y				
	Cel Win Frame	/	L N/A	Y				
	Screen Frame	/	L N/A	Y				
A #	Cellar Win Sill	/	A/M L N/A	Y				
	Cel Win Sash	/	L N/A	Y				
	Cel Win Frame	/	L N/A	Y				
	Screen Frame	/	L N/A	Y				
A	Foundation	/	L N/A	Y				
	Bulkhead	/	L N/A	Y				
	Fences	/	L N/A	Y				
	Shutters	/	L N/A	Y				
A	Newel post	/	L N/A	Y				
	Railing Cap	/	A/M L N/A	Y				
	Handrail	/	A/M L N/A	Y				
	Balusters	/	L N/A	Y				
	Lower Rail	/	L N/A	Y				
	Treads	/	F L N/A	Y				
	Risers	/	L N/A	Y				
	Tread Edge	/	L N/A	Y				
	Landing floor	/	L N/A	Y				
	Stringer	/	L N/A	Y				
	Lattice	/	L N/A	Y				
A	Drain Pipes	/	L N/A	Y				
	Elec Conduit	/	L N/A	Y				
	Oil Fill Pipe	/	L N/A	Y				
	Overhang Trim	/	L N/A	Y				
A	Lamp Post	/	L N/A	Y				
A	Flag Pole	99	F M/I A/M 0 N/A	Y				
A		/	F M/I A/M L N/A	Y				

Soil Test Results (Must be less than 400 ppm for play area / 1200 ppm bare soil)

LOCATION	AREA MEASUREMENT (Square Feet)	RESULT (PPM)	REMED DATE	REMED METH
Play Area				
Bare Soil				

Comments:

MEL BLACKMAN — Inspector (print) | M-1377 — Lic # | Signature | 08- 27 - 2018 — Date

MEL BLACKMAN — Risk Assessor (print) | R-1377 — Lic # | Signature | / / — Date

Page 25 Of 38 (38 / 40)

Address of Property: 145 MAIN ST. Apt # DAYCARE City: GROTON

EXTERIOR B Side

SIDE B	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
B	Siding	N.C	L N/A	Y				
	Corner Boards	/	L N/A	Y				
	Lower Trim	/	L N/A	Y				
	Upper Trim	CN	L N/A	Y				
	Win Above 5'	VR	L N/A	Y				
	Porch Above 5'	/	L N/A	Y				
B 12 34	Storm Door	/	L N/A	Y				
	Strm Door Edge	/	F L N/A	Y				
	Door	0.0	L N/A	Y				
	Door Edge	/	F L N/A	Y				
	Door Casing	0.1	L N/A	Y				
	Door Jamb	0.2	F L N/A	Y				
	Threshold	/	L N/A	Y				
	Kickplate	/	L N/A	Y				
B 12 4	Storm Door	/	L N/A	Y				
	Strm Door Edge	/	F L N/A	Y				
	Door	0.2	L N/A	Y				
	Door Edge	/	F L N/A	Y				
	Door Casing	0.0	L N/A	Y				
	Door Jamb	0.0	F L N/A	Y				
	Threshold	/	L N/A	Y				
	Kickplate	/	L N/A	Y				
B 12 34	Door	/	L N/A	Y				
	Door Edge	/	F L N/A	Y				
	Door Casing	/	L N/A	Y				
	Door Jamb	/	F L N/A	Y				
	Threshold	/	L N/A	Y				
	Kickplate	/	L N/A	Y				
B #	Window Sill	/	A/M L N/A	Y				
	Win Casing	/	L N/A	Y				
	Window Sash	/	L N/A	Y				
B #	Window Sill	/	A/M L N/A	Y				
	Win Casing	/	L N/A	Y				
	Window Sash	/	L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in this box can only be made intact by a Deleader (MORE THAN 2880 SQ. IN.)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD
B				
B				
B				

SIDE B	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
B #	Window Sill	/	A/M L N/A	Y				
	Win Casing	/	L N/A	Y				
	Window Sash	/	L N/A	Y				
B # X14	Cellar Win Sill	CN	A/M L N/A	Y				
	Cel Win Sash	VR	L N/A	Y				
	Cel Win Frame	CN	L N/A	Y				
	Screen Frame	/	L N/A	Y				
B #	Cellar Win Sill	/	A/M L N/A	Y				
	Cel Win Sash	/	L N/A	Y				
	Cel Win Frame	/	L N/A	Y				
	Screen Frame	/	L N/A	Y				
B #	Cellar Win Sill	/	A/M L N/A	Y				
	Cel Win Sash	/	L N/A	Y				
	Cel Win Frame	/	L N/A	Y				
	Screen Frame	/	L N/A	Y				
B	Foundation	/	L N/A	Y				
	Bulkhead	/	L N/A	Y				
	Fences	/	L N/A	Y				
	Shutters	/	L N/A	Y				
B	Newel post	1.3	L N/A	Y				
	Railing Cap	2.0	A/M D N/A	Y				
	Handrail metal	2.3	A/M Q N/A	Y				
	Balusters	/	L N/A	Y				
	Lower Rail metal	1.7	Q N/A	Y				
	W.P. Metal	1.2	Q N/A	Y				
	Risers Treat	N.C	L N/A	Y				
	Tread Edge	/	L N/A	Y				
	Landing floor	/	L N/A	Y				
	Stringer	/	L N/A	Y				
	~~Lattice~~ Lattice	NA	Q N/A	Y				
B	Drain Pipes	/	L N/A	Y				
	Elec Conduit	/	L N/A	Y				
	Oil Fill Pipe	/	L N/A	Y				
	Overhang Trim	/	L N/A	Y				
B	Lamp Post	/	L N/A	Y				
B	Overhang	0.0	F M/ A/M L N/A	Y				
B		/	F M/ A/M L N/A	Y				

Soil Test Results (Must be less than 400 ppm for play area / 1200 ppm bare soil)

LOCATION	AREA MEASUREMENT (Square Feet)	RESULT (PPM)	REMED DATE	REMED METH
Play Area				
Bare Soil				

Comments:

MEL BLACKMAN	M-1377	[signature]	08- 27 - 2018	Page 37 of 38
Inspector (print)	Lic #	Signature	Date	39 40
MEL BLACKMAN	R-1377		/ /	
Risk Assessor (print)	Lic #	Signature	Date	

Address of Property: 145 MAIN ST. Apt # DAYCARE City: GROTON

EXTERIOR C Side

SIDE C	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
C	Siding	NC	L N/A	Y				
	Corner Boards	/	L N/A	Y				
	Lower Trim	/	L N/A	Y				
	Upper Trim	CN	L N/A	Y				
	Win Above 5'	WL	L N/A	Y				
	Porch Above 5'	/	L N/A	Y				
C 1 2 3 4	Storm Door	/	L N/A	Y				
	Strm Door Edge	/	F L N/A	Y				
	Door	0.2	L N/A	Y				
	Door Edge	/	F L N/A	Y				
	Door Casing	0.1	L N/A	Y				
	Door Jamb	0.0	F L N/A	Y				
	Threshold	CN	L N/A	Y				
	Kickplate	/	L N/A	Y				
C 1 2 4	Storm Door	/	L N/A	Y				
	Strm Door Edge	/	F L N/A	Y				
	Door	0.0	L N/A	Y				
	Door Edge	/	F L N/A	Y				
	Door Casing	0.4	L N/A	Y				
	Door Jamb	0.1	F L N/A	Y				
	Threshold	CN	L N/A	Y				
	Kickplate	/	L N/A	Y				
C 1 2 3 4	Door	0.3	L N/A	Y				
	Door Edge	/	F L N/A	Y				
	Door Casing	0.0	L N/A	Y				
	Door Jamb	0.0	F L N/A	Y				
	Threshold	CN	L N/A	Y				
	Kickplate	/	L N/A	Y				
C #	Window Sill	CN	A/M L N/A	Y				
	Win Casing	CN	L N/A	Y				
	Window Sash	WL	L N/A	Y				
C #	Window Sill	/	A/M L N/A	Y				
	Win Casing	/	L N/A	Y				
	Window Sash	/	L N/A	Y				

SIDE C	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
C #	Window Sill	/	A/M L N/A	Y				
	Win Casing	/	L N/A	Y				
	Window Sash	/	L N/A	Y				
C #	Cellar Win Sill	/	A/M L N/A	Y				
	Cel Win Sash	/	L N/A	Y				
	Cel Win Frame	/	L N/A	Y				
	Screen Frame	/	L N/A	Y				
C #	Cellar Win Sill	/	A/M L N/A	Y				
	Cel Win Sash	/	L N/A	Y				
	Cel Win Frame	/	L N/A	Y				
	Screen Frame	/	L N/A	Y				
C #	Cellar Win Sill	/	A/M L N/A	Y				
	Cel Win Sash	/	L N/A	Y				
	Cel Win Frame	/	L N/A	Y				
	Screen Frame	/	L N/A	Y				
C	Foundation	/	L N/A	Y				
	Bulkhead	/	L N/A	Y				
	Fences	/	L N/A	Y				
	Shutters	/	L N/A	Y				
C	Newel post	NC	L N/A	Y				
	Railing Cap	NC	A/M L N/A	Y				
	Handrail	0.1	A/M L N/A	Y				
	Balusters	NC	L N/A	Y				
	Lower Rail	NC	L N/A	Y				
	Treads	NC	F L N/A	Y				
	Risers	0.2	L N/A	Y				
	Tread Edge	/	L N/A	Y				
	Landing floor	NC	L N/A	Y				
	Stringer	NC	L N/A	Y				
	Lattice	/	L N/A	Y				
C	Drain Pipes	/	L N/A	Y				
	Elec Conduit	/	L N/A	Y				
	Oil Fill Pipe	/	L N/A	Y				
	Overhang Trim	/	L N/A	Y				
C	Lamp Post	/	L N/A	Y				
C	4 Side/Kick	0.2	F MI A/M L N/A	Y				
C		/	F MI A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

Play Ground Tested 6/16/23 All paints 0.1 JPC
Picnic Tables 0.1 Bench 0.1 JPC

EXCLUDED SURFACES: Surfaces listed in this box can only be made intact by a Deleader (MORE THAN 2880 SQ. IN.)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD
C				
C				
C				

Soil Test Results (Must be less than 400 ppm for play area / 1200 ppm bare soil)

LOCATION	AREA MEASUREMENT (Square Feet)	RESULT (PPM)	REMED DATE	REMED METH
Play Area				
Bare Soil				

Comments:

MEL BLACKMAN	M-1377		08- 27 - 2018
Inspector (print)	Lic #	Signature	Date
MEL BLACKMAN	R-1377		/ /
Risk Assessor (print)	Lic #	Signature	Date

Page ~~38~~ 40 Of ~~38~~ 40

ress of Property: 145 MAIN ST. Apt # DAYCARE City: GROTON

EXTERIOR D Side

SIDE D	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
D	Siding	NC	L N/A	Y				
	Corner Boards	.	L N/A	Y				
	Lower Trim	—	L N/A	Y				
	Upper Trim	NT	L N/A	Y				
	Win Above 5'	VR	L N/A	Y				
	Porch Above 5'	/	L N/A	Y				
D	Storm Door	/	L N/A	Y				
	Strm Door Edge	.	F L N/A	Y				
	Door	0.0	L N/A	Y				
1 2	Door Edge	/	F L N/A	Y				
3 4	Door Casing	02	L N/A	Y				
	Door Jamb	0.0	F L N/A	Y				
	Threshold	CN	L N/A	Y				
	Kickplate	/	L N/A	Y				
D	Storm Door	/	L N/A	Y				
	Strm Door Edge	.	F L N/A	Y				
	Door	9.9	D N/A	Y				
1 2	Door Edge	5.8	G D N/A	Y				
3 4	Door Casing	99	D N/A	Y				
	Door Jamb	4.7	G D N/A	Y				
	Threshold	NC	L N/A	Y				
	Kickplate	.	L N/A	Y				
D	Door	.	L N/A	Y				
	Door Edge	.	F L N/A	Y				
1 2	Door Casing	.	L N/A	Y				
3 4	Door Jamb	.	F L N/A	Y				
	Threshold	.	L N/A	Y				
	Kickplate	.	L N/A	Y				
D	Window Sill		A/M L N/A	Y				
	Win Casing	.	L N/A	Y				
#	Window Sash	.	L N/A	Y				
D	Railing	2.6	G D N/A	Y				
	Lower Rail	1.5	D N/A	Y				
#	Newel Post	9.9	D N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

AT CANOPY

EXCLUDED SURFACES: Surfaces listed in this box can only be made intact by a Deleader (MORE THAN 2880 SQ. IN.)

SIDE	LOCATION	MEASURE: LOOSE PAINT	IC DATE	IC METHOD
D				
D				
D				

SIDE D	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
D	Window Sill	.	A/M L N/A	Y				
	Win Casing	/	L N/A	Y				
#	Window Sash	.	L N/A	Y				
D	Cellar Win Sill	CN	A/M L N/A	Y				
	Cel Win Sash	VR	L N/A	Y				
#	Cel Win Frame	CN	L N/A	Y				
	Screen Frame	/	L N/A	Y				
D	Cellar Win Sill	.	A/M L N/A	Y				
	Cel Win Sash	.	L N/A	Y				
#	Cel Win Frame	.	L N/A	Y				
	Screen Frame	.	L N/A	Y				
D	Cellar Win Sill	.	A/M L N/A	Y				
	Cel Win Sash	/	L N/A	Y				
#	Cel Win Frame	.	L N/A	Y				
	Screen Frame	.	L N/A	Y				
D	Foundation	.	L N/A	Y				
	Bulkhead	.	L N/A	Y				
	Fences	.	L N/A	Y				
	Shutters	.	L N/A	Y				
D	Newel post	00	L N/A	Y				
	Railing Cap	02	A/M L N/A	Y				
	Handrail	03	A/M L N/A	Y				
	Balusters	02	L N/A	Y				
	Lower Rail	01	L N/A	Y				
	Treads	.	F L N/A	Y				
	Risers	.	L N/A	Y				
	Tread Edge	.	L N/A	Y				
	Landing floor	.	L N/A	Y				
	Stringer	.	L N/A	Y				
	Lattice	.	L N/A	Y				
D	Drain Pipes	.	L N/A	Y				
	Elec Conduit	.	L N/A	Y				
	Oil Fill Pipe	.	L N/A	Y				
	Overhang Trim	.	L N/A	Y				
D	Lamp Post	.	L N/A	Y				
D	Handrail	0.6	F M/I A/M L N/A	Y				
D	Overhang	0.3	F M/I A/M L N/A	Y				

Soil Test Results (Must be less than 400 ppm for play area / 1200 ppm bare soil)

LOCATION	AREA MEASUREMENT (Square Feet)	RESULT (PPM)	REMED DATE	REMED METH
Play Area				
Bare Soil				

Comments: